

Damage Prevention Committee Meeting Case List

Feb. 10, 2026

Omnibus Session

Case Number	Stakeholders	Summary	Violations & Recommendation
59253	Contractor/Excavator: Caddick Utilities Project Owner: Aqua America Designer: TOTAL ENGINEERING AND CONSULTING LLC Other: Homeowner	<u>On 6/27/2025 8:00:00 AM at 242 N. Penn St., HATBORO BORO, MONTGOMERY</u> The incident occurred on 6/27/2025, at 8:00 AM, on 242 N Penn St, in Hatboro Boro, Montgomery County. A sewer line owned by a homeowner was damaged. Caddick Utilities is the excavator. Their AVR states, "On June 27th, 2025, while installing a new 12" water main, we unknowingly damaged a sanitary sewer lateral for house number 242 N. Penn St., Hatboro. The depth of the lateral was 5' from surface, and our excavation was down to 5' depth, so we never saw the lateral while installing the water main. The sewer main and the lateral connection point were correctly marked, but the lateral was not marked. On September 8th, the damaged sewer lateral showed itself as sewage backed up into the homeowner's bath tub. They then called a plumber who snaked the line and incorrectly informed the homeowners that the line was damaged in their yard, and would need a full replacement. The homeowner, not knowing any better, agreed to allow the plumber to replace the line at a cost of roughly \$12000.00. Then the line backed up again, and they called the plumber back, who then scoped the line and found the damage in the street, under our new 12" water main, which he should have done the first time, which would have saved the homeowner all that money. The homeowners have since been informed and made aware that the plumber's initial diagnosis was incorrect, and are going to lodge a complaint with the PUC, and are going to request a refund from the plumber - if the plumber had done his job correctly, it would have cost the homeowners nothing except the trouble-shoot cost for the plumbers initial diagnosis." Aqua Pennsylvania is the project owner. Their AVR states, "Aqua Contractor Caddick Utilities, on June 27th, 2025, while installing a new 12" water main, they unknowingly damaged a sanitary sewer lateral for house number 242 N Penn St, Hatboro. The depth of the lateral was 5' from surface and the excavation was down to 5' depth, and the crew never saw the lateral while installing the water main. The sewer main and the lateral connection point were correctly marked, but the lateral was not marked. On September 8th, the damaged sewer lateral showed itself as sewage backed up into the homeowner's bath tub. They customer called a plumber who snaked the line and incorrectly informed the homeowners that the line was damaged in their yard, and would need a full replacement. The homeowner not	

Case Number	Stakeholders	Summary	Violations & Recommendation
		knowing any better, agreed to allow the plumber to replace the line at a cost of roughly \$12,000.00 Then the line backed up again, and they called the plumber back, who then scooped the line and found the damage in the street under our new 12" water main, which the plumber should have done the first time, which would have saved the homeowner money. The homeowners have since been informed and made aware that the plumber's initial diagnosis was incorrect, and are going to lodge a complaint with the PUC and are going to request a refund from the plumber. AVR filed by Project Owner when information was sent to us.” Ticket #20252531370 New – Damage – Emergency was entered on 9/10/25 which was when the excavator and project owner were informed of the damage that occurred to the line. No photos of the original excavation on 6/27/2025 were submitted, or of the repair. While the damaged sewer lateral is in the same location as the excavation that occurred on 6/27/2025, there is no evidence that the damage is a direct result of the excavation, as defined in Act 127 of 2024. The following tickets were included by PA One Call but are not for the township where the damage occurred: 20230121380, 20230121380, 20243391155, 20220261470 Violations: There is no evidence of damage that occurred as a direct result of excavation, as defined in Act 127 of 2024.	
58730	Facility Owner: PHILADELPHIA GAS WORKS Contractor/Excavator: MINI BACKHOE SERVICES LLC Project Owner: CAWLEY MASONRY Other: HOMEOWNER	<u>On 7/23/2025 8:00:00 AM at 8803 CREFELD ST, PHILADELPHIA CITY, PHILADELPHIA</u> The incident occurred on 7/23/2025 at 8803 Crefeld St in Philadelphia City in Philadelphia Co. An emergency ticket was submitted for routine work. Philadelphia Gas Works the facility owner stated in their Alleged Violation Report (AVR) that “This person put a one-call ticket in as an emergency for repairing a sidewalk, driveway, and walkway. This should be planned work and a routine ticket. PA Act 287 of 1974, as amended, defines an Emergency as: "...a sudden or unforeseen occurrence involving a clear and immediate danger to life, property, and the environment, including, but not limited to, serious breaks or defects in a facility owner's lines". On 10/03/2025 DPI Maki sent an email asking if there were any pictures of the excavation. MINI BACKHOE SERVICES LLC submitted an AVR on 10/03/2025 promptly after DPI Maki sent an email asking for an AVR. The emergency ticket states that the work is being done for MINI BACKHOE SERVICES. The address is a residential address. They stated in their AVR that “We were working under and for a masonry contractor as a subcontractor and we were told not only would we be breaking up the driveway apron (routine work) but we would also be digging up a broken sewer line that needed to be repaired due to raw sewage	MINI BACKHOE SERVICES LLC: \$1,500.00 Section 5(9) 1st Offense \$1,000.00 Section 5(6)(i) 2nd Offense \$500.00 Section 5(17) 1st Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		backing into the house. I couldn't assemble a crew for next day repair but I was able to get onsite 2 days later to fix the sewer. It wasn't until the driveway apron was jack hammered and removed by us that we were told the sewer was snaked clear and didn't have to be excavated". On 10/06/2025 DPI Maki asked for contact information about the project owners: The excavator who subcontracted Mini Backhoe Services and the Homeowner who hired them. On 10/06/2025 am email was received from MBS LLC which stated that "Unfortunately I don't have any information on the sewer as I was a 3rd party who was contracted through a masonry company who in turn was working for the homeowner. I couldn't even tell you the homeowners name because we had zero contact with them and I can't find any information about the masonry contractor either because it was a quick 1 day cash job and, in those situations, we just get it done and move on to the next job". On 10/06/2025 DPI Maki sent an email asking who asked MINI BACKHOE SERVICES LLC to repair the sewer. On this same day an email was received back stating that MBS does not know who hired them and that they are feeling head hunted. DPI responded back explaining why an AVR was received and that this is being investigated, noting the information that was provided. On 10/16/2025, after the AVR request letter was sent to Cawley Masonry, An email was received from Jason Criniti of Mini Backhoe Services stated that he found who hired him and named Cawley Masonry and named "John" and added that he found his telephone number. On 10/06/2025 DPI sent an AVR request letter to the homeowner. Homeowner Lisa Mancuso called in on 10/16/2025 and spoke with DPI Maki. She stated that she will provide an email with detailed information about the project this evening. She also stated that Cawley Masonry was hired to replace the old, cracked driveway at this home. On 10/17/2025 an email was received from the homeowner which stated that "We had Cawley Masonry Inc. replace the 100+ year-old cracked, pressed concrete at the foot of our driveway with some nice stone. They did things differently 100+ years ago and the concrete was thick and heavy. John and his son Jake were great guys and we could not be happier with their work". Cawley Masonry was sent an AVR request letter on 10/16/2025. CAWLEY MASONRY stated in their AVR that "We are Cawley Masonry and we hired Mini Backhoe services to remove 10" of concrete and stone. We had no issues on the site, no lines were discovered in the dig. Im not even sure why we got a violation in the mail. We believe the excavator and Pa One Call have a beef going on. We had no issues, no pipes were encountered, hit or damaged and the job is completed and everyone is happy except Pa One Call". Picture was provided. VIOLATIONS	

Case Number	Stakeholders	Summary	Violations & Recommendation
		MINI BACKHOE SERVICES is in violation of: Section 5(9) – Emergency notification 20252040472 does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. This is a second-time offense. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within 30 days of the receipt of the request. Recommendation: The penalty is applied for section 5(9) and 5(6)(i). For Section 5(17) the \$500. Penalty is reduced to a warning. Mini Backhoe Services LLC. Jason from Mini Backhoe Services LLC stated that he had no information of who hired him until DPI sent an Alleged Violation Report (AVR) request to Cawley Masonry (see email chain and when the AVR request letter was sent) then Mini Backhoe Services LLC sent an email with the name of the company and telephone number stating that he “found it”. Jason never responded to the question of how Cawley Masonry found Mini Backhoe to do the work. Email in the chain states that he had “no information” because the job was” a quick cash job”. Please also note that neither the Emergency ticket, the homeowner, or CAWLEY MASONRY mention anything about a broken sewer line, as is stated in the AVR from MINI BACKHOE SERVICES. Excavator training is required.	
57378	Facility Owner: Comcast Contractor/Excavator: Wicked Bull Enterprises Project Owner: Shentel Communications LLC.	<u>On 7/24/2025 12:00:00 PM at 1076 MONTICELLO LANE, MANOR TWP, LANCASTER</u> Comcast accepts. ***** The incident occurred on July 24th, 2025, at 12:00 PM, at 1076 Monticello Lane, in Manor Township, Lancaster County. A cable line owned by Comcast was damaged. Comcast is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/21/2025. Wicked Bull Enterprises is the excavator. An AVR has not been filed as of 10/21/2025. Shentel Glo Fiber, the project owner, submitted an AVR. Their AVR states, " The primary reason the damage occurred is due to the Comcast locator’s positive response of 001- Clear no facilities or facilities not involved based on ticket information on ticket 20251830540. Update tickets 20252022352 & 20252022358 were both had a positive response of 001- Clear no facilities or facilities not involved based on ticket information. The excavator mistakenly called in update tickets instead of a renotify tickets, therefore the excavator is at-fault for this damage for failure to call in a renotify ticket when there is clear evidence of CATV pedestals in the scope of the PA811 ticket. The damage occurred while the excavator was digging a missile pit	Comcast: \$8,000.00 Section 2(10) 3rd Offense \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00 Wicked Bull Enterprises: \$1,000.00 Section 5(16) 1st Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		struck and damaged the unmarked comcast drop conduit. It did not appear that the drop inside of the conduit was damaged.” Photos were submitted. Comcast responded “clear” to complex project ticket 20251341720, and the routine tickets: 20251830540, 20252022352, 20252022358. They had underground lines at the location and did not mark their lines for any of these tickets. The submitted photos show that the cable line was not marked and that there are no arial lines. This case is related to case 057379. Violations: Comcast- - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20251830540. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20252022352. - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20252022358. Recommendation: The penalty is applied. PUC compliance training education was recently completed. Wicked Bull Enterprises- - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.	
58356	Facility Owner: First Energy - Penelec Contractor/Excavator: MSLS Enterprises, LLC Project Owner: MSLS Enterprises, LLC	On 7/29/2025 8:00:00 AM at 510 N. 7th Street, PHILIPSBURG BORO, CENTRE Incident occurred on July 29th, 2025, at 8am on 510 North 7th Street, Philipsburg Boro, Centre County. An electric line was damaged. First Energy - Penelec's Alleged Violation Report (AVR) states, "On July 28, 2025, Penelec was notified of an outage at 510 N. 7th Street, Philipsburg, Pennsylvania. USIC, Penelec’s Contract Locator, investigated and determined that an underground electric secondary service was damaged. The root cause of the damage was the Excavator, Jimmy Brokenshire, did not	MSLS Enterprises, LLC: \$2,750.00 Section 5(2.1) 1st Offense \$1,000.00 Section 5(16) 1st Offense \$1,000.00 Section 5(21) 1st Offense \$250.00 Section 5(23) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		request the location and type of facility owner through the PA One Call System." Damage was done outside of the area covered by the ticket. Ticket was called in as a homeowner ticket but list his home residence as a different address. The address provided on the ticket is the same address as MSLS Enterprises, LLC. Email states that the caller is the co-owner of MSLS Enterprises, LLC. Are you the property owner or renter? - We are the owners and the line was damaged when the mini excavator struck the line. AVR from MSLS Enterprises, LLC was submitted on 10/27/25 and stated, "On 28-July-2025, during the dig for connecting of the electrical conduit to the mobile home 508 to the power meter, my business partner inadvertently struck an electrical cable at 508 N 7th Street Philipsburg, PA 16866. The incident was reported immediately to Penelec and all necessary safety protocols were enacted to secure the area and prevent further damage or risk to public safety. Your questions along with answers are outlined below along with our follow up." Violations: Jimmy Brokenshire Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Section 5(21) – Excavator failed to pay the annual fee for service provided by the One Call System. PUC compliance education is required. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. PUC compliance education is required.	
57714	Facility Owner: UGI Contractor/Excavator: P&W Washo Project Owner: Carbondale Corner LLC Designer: K B A ENGINEERING	On 7/31/2025 8:30:00 AM at 99 BROOKLYN ST, CARBONDALE CITY, LACKAWANNA Phone call with KBA Eng. KBA states they were acting as a "Project Manager" and did not do any designs. Violations reduced to a warning, keeping education. KBA also requested additional training - POCS contact list/liaisons provided. KBA was listed as the designer on the report due to their main roles listed on their website. Had they submitted an AVR, and provided additional information during the investigation, it could have been determined at that time what their role was. ***** The incident occurred on 7/31/2025, at 8:30 AM, on 99 Brooklyn St, in Carbondale City, Lackawanna County. A gas line owned by UGI was damaged. 911 was contacted.	P&W Washo: \$2,250.00 Section 5(23) 1st Offense \$500.00 Section 5(6)(i) 1st Offense \$250.00 Section 5(16) 1st Offense \$1,000.00 Section 5(17) 1st Offense \$500.00 K B A ENGINEERING: \$0.00 Section 4(2.5) 1st Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		UGI is the facility owner. Their Alleged Violation Report (AVR) states, "Excavator struck and damaged a correctly marked gas facility while digging in the tolerance zone. The original one call for P&W Washo was from Jan 8th 2025. KBA Engineering called in a OC ticket July 16th 2025, UGI located the facilities in the scope of the ticket for the KBA ticket. P&W Washo was excavating at the time of the damage. Both ticket numbers are attached below. P&W Washo stated that they had not been continuously working at the site since Jan 2025. P&W Washo also failed to maintain any marks from the original ticket in January." P and W Construction, also known as P&W Washo, is the excavator. An AVR has not been filed as of 09/29/2025. An AVR request letter was sent on 9/29/2025. An email was sent on 10/23/2025 asking if the AVR was submitted. No response was sent back, and no AVR was submitted as of 11/3/2025. Carbondale Corner is the project owner according to the tickets. An AVR has not been filed as of 09/29/2025. No contact information is available for them. K B A Engineering is the designer. An AVR has not been filed as of 09/29/2025. An AVR request letter was sent on 9/29/2025 asking for an AVR to be submitted, and information provided on why they submitted Ticket #20251923062 New – Excavation – Routine. No AVR, or information, was submitted as of 11/3/2025. Violations: Excavator – P and W Construction: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner's facilities in the construction area. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: PUC Online Compliance Training is required. Designer – KBA Engineering: Section 4(2.5) – Failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of request. Section 4(8) – Designer failed to submit an Alleged Violation Report through the One Call System within 30	Section 4(8) 2nd Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		business days of being notified or aware that a violation of this act may have been committed. Recommendation: PUC Online Compliance Training is required.	
57291	Facility Owner: PHILADELPHIA GAS WORKS Contractor/Excavator: PHILADELPHIA WATER DEPARTMENT Project Owner: PHILADELPHIA WATER DEPARTMENT (Placeholder)	<u>On 8/6/2025 2:03:00 PM at S BROAD ST, PHILADELPHIA CITY, PHILADELPHIA</u> The non-damage incident occurred on August 6th, 2025, at 2:03 AM, on South Broad Street, in Philadelphia City, Philadelphia County. Emergency tickets were submitted for a non-emergency. Philadelphia Gas Works, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "PWD called in an emergency ticket to install a fire suppression system to a building thats not built yet, our inspector talked to a PWD rep and they do not have a start time or date for the job. This should be planned work, they are a problem with doing planned work on emergency tickets." Photos were submitted. Philadelphia Water Department is the excavator and project owner. An AVR has not been filed as of 10/24/2025. Philadelphia Water Department generated 2 emergency tickets for work that is not considered an emergency. The type of work listed on the tickets was, "INSTL 6IN FIRE CONNECTION". The property where the work was occurring was a construction site, where the building has not been built yet (as seen in photos). This work should have been planned in advance, and a routine ticket should have been placed instead of the emergency ticket. "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. Violations: Philadelphia Water Department- - Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Emergency ticket 20252183883. - Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). Emergency ticket 20252183887. Recommendation: The penalty is applied. PUC compliance training education was recently completed.	PHILADELPHIA WATER DEPARTMENT: \$1,000.00 Section 5(22) 1st Offense \$500.00 Section 5(22) 1st Offense \$500.00
57319	Facility Owner: Peoples Natural Gas Contractor/Excavator: QUAKER SALES CORPORATION	<u>On 8/6/2025 5:27:00 PM at 201 edgewood ave, LOWER YODER TWP, CAMBRIA</u> The incident occurred on 8/6/2025, at 5:27 PM, on 205 Edgewood Ave, in Lower Yoder Twp, Cambria County.	QUAKER SALES CORPORATION: \$1,250.00 Section 5(2.1) 1st Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Project Owner: LOWER YODER TWP	A gas line owned by Peoples Gas Company was damaged. Peoples Gas Company is the facility owner. Their Alleged Violation Report (AVR) states, “QUAKER SALES CORPORATION was milling on Edgewood ave in johnstown when they struck a valve box that was visible with a 1" drip stand inside. Contractor does NOT have a one-call for Edgewood ave. Contractor called in Willys st. Contractor paves over and damages curb boxes and valve boxes all the time. NO one-call for Edgewood ave Johnstown, pictures show the all of edgewood ave is milled.” Images submitted show the location, excavation, and damage. The damage is front of 201 Edgewood Ave, but is reported as in front of 205 Edgewood on their AVR. The damage is outside of the only ticket that can be found by PA One Call for this area (Ticket #20252102468). The images provided show that excavation occurred further up Edgewood as well, which is also outside of the scope of the ticket. Quaker Sales Corporation is the excavator. An AVR has not been filed as of 09/22/2025 and an AVR request was sent. They submitted an AVR on 9/25/25 which states, “AVR was not entered by Quaker Sales due to the fact that we did not physically strike a Utility. It is assumed that this was reported by the gas company. A utility valve was exposed during milling with no damage visible. It is believed that an odor of gas was reported after Quaker Sales completed their shift for the day. Gas company repaired an underground line. Milling was done on Willys Street and in the intersection of Edgewood. Address of incident is 201 Edgewood which is at the corner of these 2 streets.” No images or documents were provided. Lower Yoder Twp is the project owner. An AVR has not been filed as of 09/22/2025. Violations: Excavator - Quaker Sales Corporation: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Recommendation: PUC Online Compliance Training is required.	Section 5(6)(i) 1st Offense \$250.00
57456	Facility Owner: National Fuel Gas Contractor/Excavator: Empire Snow Management Project Owner: ERIE LAND BANK	<u>On 8/12/2025 9:31:00 AM at 427 LIBERTY ST, ERIE CITY, ERIE</u> The non-damage incident occurred on 08/12/2025, at 427 Liberty Street, in Erie City, Erie County. Non-damage event. Excavator working without a Pa One Call ticket.	Empire Snow Management: \$2,500.00 Section 5(16) 1st Offense \$1,000.00 Section 5(2.1) 1st Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		National Fuel, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, "Excavator called in a demolition ticket on 12/26/24 but never demolished the structure. On 8/12/25 excavator was discovered onsite working. Excavator never called in a new ticket and is a repeat offender." Photos were submitted. Empire Snow Management is the excavator. An AVR has not been filed as of 11/04/2025. An AVR request letter was sent 10/01/2025. Erie Land Bank is the project owner. An AVR has not been filed as of 11/04/2025. The routine ticket associated with the demolition of single family home at this location (20243611635) was requested 12/26/2024. The work was not completed. It was discovered in August of 2025 that the home was being demolished. No tickets were requested since 12/26/2024, for this location. Violations: Empire Snow Management – - Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. - Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education is required.	Section 5(17) 1st Offense \$500.00
58238	Facility Owner: UGI Project Owner: Romeo's Pizza & Pasta Other: Mohnton Borough	<u>On 8/17/2025 9:11:00 AM at 14 W Wyomissing Ave, MOHNTON BORO, BERKS</u> This incident occurred on 8/17/25 at 9:11 AM at location: 14 W Wyomissing Ave, MOHNTON BORO, BERKS County. Mohnton Boro submitted an Alleged Violation Report (AVR) that states, "A contractor struck a gas line in Mohnton Boro on August 17,2025 the town had to be evacuated and the power was turned off to most residents." An AVR report was requested from UGI and they submitted one that states, "Contractor doing a renovation of a property at the given address. This was not an excavation or demolition; it was a contractor renovating the interior of the building who cut a pipe in the basement that he did not realize was a live gas line." An AVR request was sent to the owner of the property where the damage occurred, Romeo's Pizza & Pasta, but no AVR was submitted.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		UGI indicates the damage did not occur while excavation or demolition was being performed. No images were available of the damage, or repair. Violation: No violations of Act 127 of 2024 occurred based on a review of all provided information.	
57618	Facility Owner: Verizon Contractor/Excavator: Empower Construction Project Owner: PECO Designer: TIER 1 UTILITY DESIGN INC Other: Lumen Formerly Level 3 Other: Newtown Bucks County Joint Muni Auth	<u>On 8/18/2025 8:00:00 AM at STANFORD DR, NEWTOWN TWP, BUCKS</u> PECO submitted photos that were date stamped. Violation was withdrawn. ***** The non-damage incidents occurred between August 7th, 2025, and August 21st, 2025, on Stanford Drive, in Newtown Township, Bucks County. The facility owner, Verizon, did not respond to multiple re-notify ticket requests. Verizon is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 11/04/2025. Empower Construction, the excavator, submitted an AVR. Their AVR states, “On Tuesday August 18th, 2025, an Empower Construction directional boring crew was tasked with installing new conduit on Standford Dr and Milford Ct in Newtown, PA on the Woodbourne-351 project WO#19626411. The crew began their day with conducting a job briefing and walking the project down for mark outs. As the crew was walking down the job for mark outs, it was noticed that Verizon has still not been marked out. The crew immediately stopped work, notified PECO Construction Management, PA One Call, and Empower Construction Management. PECO Construction Management informed Empower Construction to submit a Pre-AVR. Original PA1 Call Ticket #20252192855.” PECO is the project owner. An AVR has not been filed as of 11/04/2025. Routine ticket 20252192855 (version 000) had a response due date of 08/11/2025. - Verizon did not respond to this ticket. - Lumen Formerly Level 3 did not respond until 08/12/2025. - Newtown Bucks County Joint Muni Auth did not respond until 08/12/2025. - PECO replied they with scheduled mark and would mark by 08/12/2025 but did not respond ‘field marked’ until 08/18/2025. Insufficient ticket 20252192855 (version 001) had a response due date of 08/15/2025. - Verizon did not respond to this ticket. Insufficient ticket 20252192855 (version 002) had a response due date of 08/18/2025. - Verizon did not respond to this ticket.	Verizon: \$12,000.00 Section 2(5)(v) Subsequent \$2,000.00 Section 2(5)(v.1) Subsequent \$2,000.00 Section 2(5)(v.1) Subsequent \$2,000.00 Section 2(5)(v.1) Subsequent \$2,000.00 Section 2(5)(v.1) Subsequent \$2,000.00 Section 2(5)(v.1) Subsequent \$2,000.00 PECO: \$0.00 Lumen Formerly Level 3: \$500.00 Section 2(5)(v) 2nd offense \$500.00 Newtown Bucks County Joint Muni Auth: \$250.00 Section 2(5)(v) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Insufficient ticket 20252192855 (version 003) had a response due date of 08/19/2025. - Verizon did not respond to this ticket. Insufficient ticket 20252192855 (version 004) had a response due date of 08/20/2025. - Verizon did not respond to this ticket. Insufficient ticket 20252192855 (version 005) had a response due date of 08/21/2025. - Verizon did not respond to this ticket. Violations: Verizon- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20252192855 (version 000) - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252192855 (version 001) - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252192855 (version 002) - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252192855 (version 003) - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252192855 (version 004) - Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket 20252192855 (version 005) Recommendation: The penalty is applied. PUC compliance training education was recently completed. Lumen Formerly Level 3- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252192855 (version 000) Recommendation: The penalty is applied. PUC compliance training education was recently completed. Newtown Bucks County Joint Muni Auth- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252192855 (version 000) Recommendation: The penalty is applied. PUC compliance training education is required. PECO- - Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket 20252192855 (version 000) - Withdrawn. Recommendation: The penalty is applied. PUC compliance training education was recently completed.	
57951	Facility Owner: PPL Contractor/Excavator: Doli Construction Corporation Project Owner: Lower Paxton Township	<u>On 8/19/2025 11:00:00 AM at 519 RYAN DR, LOWER PAXTON TWP, DAUPHIN</u> The incident occurred on 8/19/2025, on Ryan Dr. between Scott Dr. and Lancaster Ave., in Lower Paxton township, Dauphin County.	Doli Construction Corporation: \$2,000.00 Section 5(4) 2nd Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Authority Designer: HRG INC	A single-phase primary and an electric service line was damaged. DOLI CONSTRUCTION stated in their AVR that “Crew hit electric service 4' off the mark”. Reports and pictures were included. Doli also confirmed that the foreman circles marks when they get to the site to work. LOWER PAXTON TOWNSHIP AUTHORITY stated in their AVR that “Doli's storm sewer crew hit an electric service 4' off of the mark”. Cost of the project is >\$400,000. Reports and pictures were included. HRG INC stated in their AVR that “From excavator: "Crew hit electric service 4' off the mark". Reports and pictures were provided. PPL ELECTRIC UTILITIES CORPORATION stated in their AVR that “On Tuesday, August 19, 2025, at 11:19 AM, DOLI Construction was installing sanitary main lines and services when contact was made with both a marked single-phase primary and a marked electric service. There were no injuries or harm reported as a result of this incident; however, electrical service was interrupted for multiple properties. PPL was promptly notified, and first responders were dispatched to the site. Upon arrival, the area was secured and an investigation commenced. The investigation determined that DOLI Construction operated mechanical equipment within the tolerance zone, resulting in damage to both a primary and secondary service line. Permanent repairs could not be completed on site, but temporary measures were implemented to restore power to all affected customers. DOLI Construction will be billed for crew time and materials associated with making the area safe and restoring service. Additionally, a separate work order will be created for the replacement of both the primary and service lines.” Reports and pictures were provided. On 10/06/2025 DPI Maki sent an email asking if there were any more pictures and any from before the excavation started. PPL responded right away with preconstruction/post marking pictures. Pictures show 3 lines marked where the damage occurred. PPL's email states that the circled marks were not placed by PPL. Other investigations related by tickets: 52101, 52187, 52200, 52431, 54080, 56426, and 56684 VIOLATIONS DOLI Construction Corporation is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. This is a second offense. Section 5(3) – Excavator failed to preserve mark-outs or request a remark. This is a second offense. Recommendation: The penalty is applied. Education is required. The most recent education was completed by 8/10/2025 and the incident occurred on 8/19/2025.	Section 5(3) 2nd Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
57980	Facility Owner: Service Electric Cable TV Inc. Contractor/Excavator: Zen Improvements LLC Project Owner: Homeowner Other: Astound Broadband Powered by RCN Other: Comcast Other: Verizon	<u>On 8/23/2025 1:30:00 PM at 1655 VICTORIA CIR, SALISBURY TWP, LEHIGH</u> Service Electric 2(5)(vii) Reduced from \$1000 to a warning of \$0. ***** The incident occurred on 8/23/2025, at 1:30 PM, on 1655 Victoria Cir, in Salisbury Twp, Lehigh County. A communication line owned by Service Electric Cable Tv was damaged. The facility was not notified of the damage. Service Electric Cable Tv is the facility owner. Their Alleged Violation Report (AVR) states, “On 08/23/2025, Zen Improvements LLC dug before their legal start date causing damage to communications facilities, as well as power. Ticket # 1 called in by homeowner for the contractor (20252341057) and ticket # 2 was called in by the contractor (20252350275). The excavator covered up the damage and left without alerting facility owners or PA One Call.” Zen Improvements is the excavator. An AVR has not been filed as of 09/30/2025 and an AVR request was sent the same day. No AVR was submitted as of 11/7/2025. The homeowner is the project owner. An AVR was requested but none was submitted by the homeowner. The damage was found on 8/24/2025, a day after Zen Improvements entered the routine ticket for this location, which had a dig start date of 8/28/2025. Ticket # 20252350275 New – Excavation – Routine had a response due date of 8/27/2025, and a dig date of 8/28/2025. Comcast responded “Clear.” On 8/29/2025. Ticket # 20252360033 New – Damage – Emergency was entered on 8/24/25 at 8:26 AM. Service Electric Cable TV and Astound Broadband Powered by RCN responded “Insufficient Information” on 8/24/2025 and did not enter another response. Verizon responded “Field Marked” on 8/25/2025 at 11:39 AM. Violations: Facility – Service Electric Cable TV: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252360033 Recommendation: PUC Online Compliance Training is required. Excavator - Zen Improvements LLC: Section 1.1 – Excavator did not begin within legal timeframe. Ticket # 20252350275 Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area.	Service Electric Cable TV Inc.: \$0.00 Section 2(5)(vii) 1st Offense \$0.00 Zen Improvements LLC: \$3,750.00 Section 5(7) 1st Offense \$1,000.00 Section 1.1 1st Offense \$1,000.00 Section 5(6)(i) 1st Offense \$250.00 Section 5(16) 1st Offense \$1,000.00 Section 5(17) 1st Offense \$500.00 Homeowner: \$0.00 Section 6.1(8) 1st Offense \$0.00 Astound Broadband Powered by RCN: \$1,000.00 Section 2(5)(vii) 1st Offense \$1,000.00 Comcast: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00 Verizon: \$2,500.00 Section 2(5)(vii) Subsequent \$2,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(7) – Failed to immediately report to the facility owner any break or leak in its lines, or any dent, gouge, groove, or other damage to such lines or to their coating or cathodic protection. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. Section 5(17) – Excavator failed to comply with all requests for information from PUC staff within thirty days of the receipt of the request. Recommendation: PUC Online Compliance Training is required. Project Owner – Dan Moyer: Section 6.1(8) - Project Owner failed to comply with all requests for information by the commission relating to the commission's enforcement authority under this act within 30 days of receipt of written request. This violation is issued as a warning to a homeowner. The penalty has been reduced from \$1000 to \$0. PUC Online Compliance Training is required. Facility(other) – Verizon: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252360033 Recommendation: PUC Online Compliance Training is required. Facility(other) – Astound Broadband Powered by RCN: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252360033 Recommendation: PUC Online Compliance Training is required. Facility(other) – Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket # 20252350275 Recommendation: PUC Online Compliance Training is required.	
58659	Facility Owner: VALLEY ENERGY Contractor/Excavator: Butters Homes Contractor/Excavator: M & W Contractor/Excavator: Robinson & Son Masonry Project Owner: Homeowner	On 8/24/2025 11:10:00 AM at 707 N RIVER ST, ATHENS BORO, BRADFORD Butters Homes violation and penalty is being removed after submitting their contractual obligations. Robinson and Son Masonry did not excavate. DPI removed violation and penalty. **** Incident occurred on August 24th, 2025, at 11:10am on 707 North River Street, Athens Boro, Bradford County. A gas line was damaged. Valley Energy's Alleged Violation Report (AVR) states, "On August 24th, 2025, Valley Energy's natural gas service located at 707 N. River St. Athens PA was damaged by an excavator while digging with mechanized equipment. There are several factors with this AVR. The ticket's lawful start date was 8/6/2025 through 8/15/2025, but the damage occurred on	Butters Homes: \$0.00 M & W: \$2,500.00 Section 5(8) 1st Offense \$1,000.00 Section 5(16) 1st Offense \$1,000.00 Section 5(23) 1st Offense \$500.00 Robinson & Son Masonry: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		8/24/2025. Also, the ticket was called in by the homeowner, Brenda Vanderpool. But the damage was done by Brian Wood of M&W Trucking. A contractor working for the homeowner. The Valley Energy Crew reported that in the location of the damage, the flagging didn't match the paint on the ground, and the suspicion was that the flags were moved to indicate an improper locate. The contractor indicated to the Valley Energy crew that the line was incorrectly located. Upon further investigation, after repairs were made, there is evidence to suggest that the flags were not in their original location. I have submitted photographs of before and after the damage to showcase that the flags were moved from their original location. Looking at before picture 1, if you zoom in you can see the fourth yellow flag in the center of the yard and several feet away from the dirt pile. Prior this flag the service bends to the North. This is also depicted on the map image Screenshot GIS 707 N River Service. The Before picture 2 has an even better view of the flags clearly several feet away from the dirt pile in the location of the damage. Also, if you look at After picture 1 & 2, you can see the flags are not in the original location and right next to the dirt pile in the area of the damage. I can't determine how they were relocated, but they were not in the original location when Valley Energy arrived at the scene." Two routine tickets were placed by the homeowner. AVR notes that 911 was not notified. No AVR has been submitted by M&W as of 11/3/25. Ticket 20251694595 notes, "Homeowner Called for Contractor? Yes. Name of Contractor Called ROBINSON AND SONS CONCRETE." Ticket comments, "ADDITIONAL CONTRACTORS ARE M AND W DEMOLITION AND EXCAVATING. ALSO BUTTERS HOMES" Homeowner's AVR states that the excavator used an excavator prior to switching to hand tools. AVR list the homeowner as who called 911. Violations: M&W Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 20252132766 & 20251694595. PUC	

Case Number	Stakeholders	Summary	Violations & Recommendation
		compliance education is required for the excavators working onsite of this excavation or their replacements. Robinson & Son Masonry Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 20251694595. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Butters Homes Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. 20251694595. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	
57965	Facility Owner: UGI Utilities Contractor/Excavator: Baker Masonry Project Owner: Homeowner	<u>On 8/25/2025 1:15:00 PM at 2303 BOAS, PENBROOK BORO, DAUPHIN</u> Incident occurred on August 25th, 2025, at 1:15pm on 2303 Boas Street, Penbrook Boro, Dauphin County. A gas line was damaged. UGI's Alleged Violation Report (AVR) states, "Jeremy Baker of Baker Masonry was using a mini excavator to pull up old sidewalk. The excavator was digging with mechanized equipment in the established tolerance zone. As a result, the gas service to 2303 Boas St, Harrisburg was struck and pulled causing 1/2" plastic line to tear in half. The excavator also delegated his sole responsibility of submitting the locate request to the homeowner of the property." AVR notes that 911 was notified. Ticket 20252304462 was placed by the homeowner on 8/18/25. Damage was done on 8/25/25, and the excavator called in a routine ticket on 8/26/25. No AVR has been received from Baker Masonry or the homeowner as of 10/22/25. Images show the excavator and damaged gas line marked within the tolerance zone. Homeowner called in the ticket prior to hiring Baker Masonry. Homeowner called and stated that the excavator was hit the gas line with an excavator while he was outside. Violations: Baker Masonry Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. PUC compliance education is required. Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. PUC compliance education is required.	Baker Masonry: \$2,500.00 Section 5(2.1) 1st Offense \$1,000.00 Section 5(4) 1st Offense \$500.00 Section 5(16) 1st Offense \$1,000.00 Section 5(23) 1st Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or other violation. PUC compliance education is required. Section 5(23) – Excavator may not delegate their duty to submit a locate request to the One Call System to another person. The excavator shall have sole responsibility to submit each locate request to the One Call System. PUC compliance education is required. Reduced to warning for taking corrective action to place a ticket the day after the damage occurred.	
57860	Facility Owner: Comcast Facility Owner: First Energy - Met-Ed Contractor/Excavator: A H MOYER	On 8/26/2025 7:15:00 AM at EAST DR, NORTH LEBANON TWP, LEBANON Incident occurred on August 26th, 2025, at 7:15am along East Drive, North Lebanon Township, Lebanon County. Non-damage violation of Act 127 of 2024. A H Moyer's Alleged Violation Report (AVR) states, "WHOEVER IS SUPPOSED TO MARK ELECTRIC WILL NOT COMPLETE THE TICKETS - THEY JUST KEEP PUSHING THE DATE OUT FARTHER AND FARTHER, I KEEP CALLING IN RENOTIFY.... THIS PARTICULAR TICKET HAS BEEN OPEN SINCE THE MIDDLE OF JULY I HAVE HAD 5 TICKETS, 2 OF THEM DAMAGES ON THIS PARTICULAR AREA AND STILL MET ED WONT COMPLETE THEIR MARKING... ONE OF THE 811 THE TICKET CLOSED ON 8/20 AND IT STILL SAYS THAT THE LINES WILL BE MARKED BY 8/18/25.... THE NEXT NEXT 811 IS 20252262385- THIS IS A DAMAGE- THEY RESPONDED CLEAR NO FACILITIES. NEXT IS 20252302236 LEGAL DATES 8/21-9/2 THEIR RESPONSE IS THAT LINES WILL BE MARKED BY 8/20..... TODAY 8/26 I JUST CALLED IN A RENOTIFY BECAUSE THERE ARE NO ELECTRIC MARKS ON THE EASTERN ROW OF TRAILERS. WE ARE SUPPOSING THAT THEY ARE PRESENT.... SINCE THE TRAILERS PROBABLY HAVE ELECTRIC. AND JUST A REMINDER- THIS IS THE JOB WHERE NO ONE CAME TO THE COMPLEX 811 MEETING -PRIOR TO THE START OF WORK... YOU GUYS JUST FINED ME FOR NOT DOING A COMPLEX TICKET WHEN I SHOULD HAVE- YOU CAN SEE THAT THIS IS GOING SO MUCH BETTER AS A COMPLEX TICKET. WHEN WE WERE HERE IN THE END OF 2024- I DIDNT HAVE THIS AS A COMPLEX PROJECT, I JUST HAD SEVERAL ONE CALLS OPEN... I THINK WE HAD 1 DAMAGE AND I MIGHT HAVE DONE 1 RENOTIFY.... SO EITHER THE USIC PEOPLE GOT WAY WORSE OR THEY THINK THAT BECAUSE IT IS A COMPLEX TICKET THEY HAVE MORE LENIENCY AND DONT HAVE TO RESPOND PROPERLY. THE PEOPLE WHO ANSWER THE 811 CALLS ARE STARTING TO REMEMBER ME AND THIS PROJECT BECAUSE I HAVE TALKED TO SOME OF THEM REPEATEDLY.... THIS IS VERY UN IMPRESSIVE FOR THE WHOLE 811 PROCESS. NOT TO MENTION- I HAVE MAPS ATTACHED, PROJECT	Comcast: \$4,000.00 Section 2(5)(v.2) 2nd Offense \$500.00 Section 2(5)(v.2) 2nd Offense \$500.00 Section 2(5)(vii) 2nd Offense \$1,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00 First Energy - Met-Ed: \$500.00 Section 2(5)(v.2) 1st Offense \$250.00 Section 2(5)(v.2) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		SKETCHES WHATEVER..... AND NO ONE CALLS ME.... THATS THE OTHER THING- THEY ARE JUST PUSHING THE DATE OUT BUT NO DISUCSSION OR PHONE NOTIFICATION.... AND THEY ARENT CLOSING THEIR TICKETS.... SO WHETHER OR NOT THEY ACTUALLY MARKED BY 8/20 -6 DAYS AGO- I DONT KNOW, SEEMS LIKE MAYBE NOT. THANKS AGAIN FOR THE NONSENSE FINES FOR A TIT-FOR TAT GAME WITH UGL..... MAYBE THE EFFORTS SHOULD BE REDIRECTED TO WHERE THERE IS A SERIOUS PROBLEM. ALSO I JUST DID AN AVR LAST WEEK THAT I WOULD HAVE LINKED BUT IT ISNT SHOWING UP ON THE PORTAL THAT IT WAS EVEN SUBMITTED. I THINK I ACTUALLY DID MORE THAN ONE ON THIS PARK BUT THE ONLY ONES SHOWING ARE FROM THE BEGINNING OF JULY. I SERIOUSLY DONT HAVE TIME TO DO AN AVR FOR EVERYTIME THEY MESS SOMETHING UP ON THIS JOB..." Case is related to 056546 where Comcast, Verizon, and First Energy's Met-Ed was given violations for not attending the complex meeting despite responding to the ticket as will attend meeting. Therefore, no mark out agreement was made due to not attending the complex meeting. Seven emergency damage tickets were placed during this project per the saved report document from Coordinate PA. Ticket 20252183564 responses: First Energy's Met-Ed - Scheduled Mark 8/8/25 at 3:34pm, Scheduled Mark 8/11/25 2:46pm, and Scheduled Mark 8/14/25 12:54pm. Final response of field marked placed 20 days late on 8/26/25 at 10:04am. Comcast - Scheduled Mark 8/8/25 at 3:33pm, Scheduled Mark 8/11/25 2:44pm, and Scheduled Mark 8/14/25 12:52pm. Final response of field marked placed 20 days late on 8/26/25 at 10:02am. 20252302236-00 Responses: First Energy's Met-Ed - Scheduled Mark 8/20/25 at 4:21pm. See Renotify -01 for final response on 8/26/25. Comcast - Scheduled Mark 8/20/25 at 4:19 pm. See Renotify -01 for final response on 8/26/25. 20252302236-01 Responses: First Energy's Met-Ed - No response 8/26/25 at 9:17am. Field Mark 8/26/25 at 9:45am. Comcast - No response 8/26/25 at 9:17am. Scheduled Mark 8/26/25 at 9:42am. Emergency Ticket 20252262385 placed on 8/14/25. Comcast didn't field mark until 8/26/25 according to other tickets. Comcast Insufficient Do not dig. Emergency Ticket 20252302340 placed on 8/18/25. Comcast didn't field mark until 8/26/25 according to other tickets.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Comcast Insufficient Do not dig. Violations: First Energy's Met-Ed Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20252183564. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20252302236. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Comcast Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20252183564. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20252302236. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252262385. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252302340. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
57931	Facility Owner: PECO Contractor/Excavator: CROSSLAND EXCAVATION	<u>On 8/26/2025 3:43:00 PM at 4663 LANDISVILLE RD, BUCKINGHAM TWP, BUCKS</u> Incident occurred on August 26th, 2025, at 3:43pm on 4663 Landisville Road, Buckingham Township, Bucks County. Non-damage incident. PECO's Alleged Violation Report (AVR) states, "FALSE EMERGENCY FOR TEST HOLES" Emergency ticket 20252384300 was placed on 8/26/25 at 3:42pm for test holes. A routine ticket was placed at 4:13pm. Emergency ticket was called in. Violation: Crossland Excavation Section 5(22) – Excavator provided a misrepresentation of an emergency excavation, subject to an administrative penalty imposed under section 7(10). 20252384300. PUC compliance education is required for the excavators working onsite of this excavation or their replacements.	CROSSLAND EXCAVATION: \$250.00 Section 5(22) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Reduced penalty by 50% for updating ticket. \$500 to \$250.	
57941	Facility Owner: PEOPLES NATURAL GAS Contractor/Excavator: INDEPENDENT ENTERPRISES Project Owner: Pittsburgh Water Designer: G A I CONSULTANTS INC Designer: WHITMAN REQUARDT & ASSOCIATES LLP	<u>On 8/27/2025 8:28:00 AM at 3474 SHADELAND AVE. PITTSBURGH CITY, ALLEGHENY</u> Independent Enterprises Inc, penalty and violation have been removed. See attachments. ***** The incident occurred on Wednesday, August 27, 2025, at 3474 Shadeland Avenue, in Pittsburgh City, Allegheny County. Peoples Natural Gas (PNG) line was damaged. PNG stated in their alleged violation report (AVR), on 8/27/2025, Independent Enterprises struck an accurately marked PNG SL main to curb while digging to install water mains and services. PNG provided photos showing damage within the tolerance zone. Independent Enterprises stated in their AVR, a gas line mark was within acceptable distance. The gas line was approximately 15" below road, right where the road base stopped. The line was struck while removing road base. The Operator was excavating road base, and the gas line was struck, the gas line was touching the road base. At 8:20am the gas line was struck, at 8:22am 911 was called, at 8:30am the Fire Department arrived. At 9:15am the gas companies Columbia and PNG arrived, and it was determined to be a PNG line. At 9:30am the line was plugged and the Contractor returned to work, at 10:29am the line was repaired. GAI Consultants, the designer, stated in their AVR, the gas line mark was within acceptable distance. The gas line was approximately 15" below road surface (directly below where pavement base stopped). The line was struck while removing road base. The Operator was excavating road base, and the gas line was struck, the gas line was touching the road base. At 8:20am the gas line was struck, at 8:22am 911 was called, at 8:30am the Fire Department arrived. At 9:15am the gas companies Columbia and PNG arrived, and it was determined to be a PNG line. At 9:30am the line was plugged and the Contractor returned to work, at 10:29am the line was repaired. Final Design One Call was run by GAI Consultants on Fri 12.19.2024, which was within the required 10 to 90-day window prior to the end of final design. PA One Call info and Utility List were noted on the plan. The total project value is over \$400,000 and during design SUE up to Quality Level (QL) A was performed. Record Drawing Research (QL-D) was done by the whole project team as the project moved through design. The surface expressions of utilities such as manholes, curb boxes, and valve boxes were surveyed (QL-C). The project owner had GAI include the cost to hire a utility locator as a subcontractor. That was Lexis Group. They connected to the locate wires and metallic pipes to use mark utility locations across the job (QL-B). The surveyor surveyed the paint markings. GAI identified	INDEPENDENT ENTERPRISES: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		places where the QL-B needed clarification and had Lexis do Test Pits (QL-A) there. Training was previously assigned to GAI for Case 17347 (training completed on Fri 6.10.2022) and Case 030748 (training completed on Fri 3.17.2023). Violation: *Independent Enterprises is in violation of section: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. Recommendation: Penalty Applied	
59183	Facility Owner: COMCAST Contractor/Excavator: LEBANON AUTHORITY CITY OF Project Owner: LEBANON WATER AUTHORITY	On 8/28/2025 9:31:00 AM at 1432 ESTHER DR, SOUTH LEBANON TWP, LEBANON The incident occurred on Thursday, August 28, 2025, at 1432 Esther Drive, in South Lebanon Township, Lebanon County. A communication line owned by Comcast was damaged. Comcast stated in their Alleged Violation Report (AVR), damaged by digging in street. Comcast provided photos of the damaged, mis-marked line. The Lebanon Authority stated in their AVR, when digging to replace the lateral and hydrant, the telecom line was "hit", and the conduit was broken. The telecom line was not marked. The Authority put a damage ticket in and had telecom contractor come out and piece it back together. The marks of the telecom where in the back of the 1 call, photo is attached to see the markings. Photo provided show the damaged, mismarked line. Excavation Emergency ticket, 20252380257, placed on 8/26/2025, by Lebanon Authority, Type of Work: Replace Hydrant. Damage Emergency ticket, 20252400903, placed on 8/28/2025, at 9:30am On Thursday, 10/23/2025, a letter and an email was sent to Lebanon Authority requesting an AVR. The AVR was submitted on 10/24/2025, not within 30 days of the 8/28/2025 incident. Violations: *Comcast is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied. *Lebanon Authority is in violation of section: 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalty Applied, and penalty reduced by 50%. (\$1,000 to \$500). PUC Compliance Education required.	COMCAST: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00 LEBANON AUTHORITY CITY OF: \$500.00 Section 5(16) 1st Offense \$500.00
58210	Facility Owner: Columbia Gas Contractor/Excavator: PUGLIANO CONSTRUCTION CO INC	On 9/4/2025 10:30:00 AM at 1600 PARK AVE, NORTH FRANKLIN TWP, WASHINGTON The incident occurred on Thursday, September 4, 2025, at 1600 Park Avenue, in North Franklin Township, Washington County.	Columbia Gas: \$500.00 Section 2(10) 1st Offense \$500.00 PUGLIANO CONSTRUCTION CO

Case Number	Stakeholders	Summary	Violations & Recommendation
	Project Owner: PennDOT Designer: BENESCH	A gas line owned by Columbia Gas was damaged. Pugliano Construction stated in their Alleged Violation Report (AVR), We had a sub-contractor on site potholing to locate the gas line with a vac truck. They told our superintendent that they could not get around a large rock and some old asphalt so they asked our operator to slide the rock out of the way. The line was directly under the rock with no marking tape or sand to alert anyone to the depth. This resulted in a puncture/breakage. Columbia gas was contacted and they repaired the damage. Columbia Gas stated in their AVR, Pagliano Construction Co Inc., working on behalf of Penn Dot, damaged an accurately marked 2" plastic main line, while excavating for bridge and road project. Columbia Gas was notified and responded. All safety checks were completed, and repairs were made. PennDOT stated in their AVR, contractor brought in Robinson Pipe company to pothole area and locate all utility lines. Encountered hard rock and Pugliano used the mini excavator to remove the rock. While cleaning out the hole the tooth of the excavator caught the 3" gas line and broke it. No warning tape or sand was present at this location. It was later conveyed to us that this line was bored. The hit occurred at 10:45am at station 769+50. 911 was called immediately and all personnel were evacuated from the area. Gas company and fire department arrived at 11:15am. Columbia gas closed off the line and made the needed repair. Photos were provided of the damaged gas line. On Wednesday, 10/22/2025, letters and emails were sent to Columbia Gas and PennDOT requesting AVR's. Columbia Gas submitted their AVR on 10/27/2025, not within 30 business days of the 9/4/2025 incident. PennDOT submitted their AVR on 10/28/2025, and on 10/24/2025 they were having issues with submitting an AVR through the PA One Call system and were working with PA One Call to resolve the issue. Violations: *Pagliano Construction Co Inc. is in violation of section: 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner's lines at the construction work site. Recommendation: Penalty Applied *Columbia Gas is in violation of section: 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner's lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: Penalty Applied as penalty reduced by 50%. (\$1,000 to \$500)	INC: \$500.00 Section 5(6)(ii) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
59266	Facility Owner: UPPER DARBY TWP Contractor/Excavator: DELMONT UTILITIES COMPANY Project Owner: AQUA PA Designer: AQUA PA - SPACESAVER Other: BRANDYWINE CAD DESIGN Other: PECO	<u>On 9/5/2025 10:01:00 AM at 923 LINDALE AVE, UPPER DARBY TWP, DELAWARE</u> The incident occurred on 9/05/2025 at 923 Lindale Ave in UPPER DARBY TWP in DELAWARE Co. A sanitary main line was damaged. DELMONT UTILITIES COMPANY stated in their Alleged Violation Report (AVR) that “WORKING TO INSTALL A WATER SERVICE ON THE 900 BLOCK OF LINDALE AVE AND DIGGING TO EXPOSE SANITARY MAIN, HIT MAIN ON MARK”. Pictures were provided. AQUA PENNSYLVANIA INC stated in their AVR that “Aqua Contractor Delmont Utilities Company, working to install a water service on the 900 block of Lindale Ave and digging to expose sanitary main, hit main on mark. AVR filed when information was received from contractor”. UPPER DARBY TWP was sent an AVR request letter on 10/17/2025. Due by 11/16/2025. An AVR was received promptly and stated that “The incident involved Delmont damaging the Township’s sewer main located in front of 923 Lindale Avenue, around 11 AM on 9/5/25. Township administrative assistant received a call regarding the incident on 9/5/25 and Gil township sewer foreman was also notified and approved of the sewer repair on the Township sewer main. The message was also forwarded to Amrinder township L&I director for notice of any plumbing inspections needed by L&I”. Pictures were provided. VIOLATIONS DELMONT UTILITIES COMPANY is in violation of: Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. This is a second time offense. Recommendation: The penalties are applied. Excavator training is required. PECO is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20251821025. Ticket 20251821025 was submitted by DELMONT UTILITIES COMPANY- on 7/01/2025 with a response due by 7/03/2025. PECO did not respond “field marked” until 7/23/2025. This is a subsequent offense. Section 2(5)(v) – Failed to respond to routine One Call ticket 20252060767 within the required amount of time. Ticket 20252060767 was submitted by DELMONT UTILITIES COMPANY- on 7/25/2025 with a response due by 7/29/2025. PECO responded “Field Marked” on 8/04. This is a subsequent offense. Recommendation: The penalties are applied. The required training has been recently completed.	DELMONT UTILITIES COMPANY: \$1,000.00 Section 5(4) 2nd Offense \$1,000.00 PECO: \$3,000.00 Section 2(5)(v) Subsequent \$2,000.00 Section 2(5)(v) Subsequent \$1,000.00
58336	Facility Owner: NATIONAL FUEL GAS DIST RC 350	<u>On 9/8/2025 12:15:00 PM at ROUTE 6N, WASHINGTON TWP, ERIE</u> The incident occurred on	PennDOT: \$1,500.00 Section 5(4) 2nd Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Contractor/Excavator: PennDOT Project Owner: PennDOT	Monday, September 8, 2025, on RT 6N, in Washington Township, Erie County. A gas line owned by National Fuel Gas (NFG) was damaged. NFG stated in their Alleged Violation Report (AVR), the Excavator working with the PennDOT crew struck properly marked natural gas distribution service while ditching. PennDOT stated in their AVR, "A PennDOT was responding to a customer concern of a ditch that needed to be cleaned out. We were within the lawful dates of the One Call. The operator admitted he hit the line without hand digging. He stated it was his last bucket, and he only needed to take a few inches to achieve positive flow." Photos provided show the damaged gas line and locate marks. Routine ticket, 20252372657 placed on 8/25/2025, Type of Work: DITCH CLEANING, and Location Information: WORKING ON THE S SIDE OF THE ROAD. On Thursday, 10/23/2025, a letter and an email were sent to PennDOT requesting an AVR. The AVR was submitted on 10/28/2025, not within 30 days of the 9/8/2025 incident. Violations: *PennDOT is in violation of sections: 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Penalties Applied. For section 5(16) penalty reduced by 50%. (\$1,000 to \$500)	Section 5(16) 1st Offense \$500.00
58372	Facility Owner: PEOPLES NATURAL GAS COMPANY LLC Contractor/Excavator: Homeowner	<u>On 9/10/2025 10:13:00 AM at 958 PAUL ST, HEMPFIELD TWP, WESTMORELAND</u> The incident occurred on Wednesday, September 10, 2025, at 958 at Paul Street, in Hempfield Township, Westmoreland County. A gas line was damaged. Peoples Natural Gas (PNG) stated in their Alleged Violation Report (AVR), "John Tiano was digging to install a new sewer lateral when he struck the marked 1" plastic gas line at 958 Paul Street, Greensburg. PNG shut gas off and made safe." PNG provided photos of the damage line. On Wednesday, 10/22/2025, a letter and an email were sent requesting an AVR from John Tiano. John submitted an AVR on Friday, 10/24/2025, and noted working as a private individual for his fiancée. John stated in his AVR, "while operating an excavator at	Homeowner: \$0.00 Section 5(4) 1st Offense \$0.00 Section 5(16) 1st Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		a property owned by my fiancée, I struck and perforated the gas line. I immediately shut down the machine and called the Peoples Gas Company. They responded and shut off the gas. Then, as required by Peoples, I had a registered and approved plumber come out and repair the line. Peoples then came back a removed the tag and gas service was restored.” John placed a routine ticket, 20252474691 on 9/4/2025, type of work- excavating sewer line, and equipment type- mini excavator. Violations: *John Tiano is in violation of sections: 5(4) – Homeowner failed to exercise due care and employ prudent excavation techniques. 5(16) – Homeowner Failed to submit an Alleged Violation Report within 30 days of striking a line. Recommendation: Warning and zero penalties but keep the violations. PUC Compliance Education Required	
58359	Facility Owner: PENNSYLVANIA AMERICAN WATER Contractor/Excavator: ARMSTRONG UTILITIES Project Owner: ARMSTRONG UTILITIES Other: Brightspeed Other: XTO Energy Inc/Mountain Gathering LLC	On 9/11/2025 10:41:00 AM at <u>HEATHER DR, BUTLER TWP, BUTLER</u> The incident occurred on Thursday, September 11, 2025, on Heather Drive, in Butler Township, Butler County. PA American Water Company’s (PAWC) line was damaged. PAWC stated in their alleged violation report (AVR), Armstrong is installing new fiberoptic lines in this area. They directionally bored into our 8" water line. PAWC crews responded, shutting the water line off. Once the one call is good, our crew will replace the damaged water main. Approximate Number of Customers Affected: 51 + Armstrong Utilities stated in their AVR, on 9/11/2025, Armstrong's construction crew was working on installing conduit for our fiber project along Heather Drive in Meridian, PA. The crew was working under a valid PA One Call dig ticket, 20252450431. The crew was using a horizontal directional boring machine to go under Heather Drive. After they crossed Heather Drive the boring drill head struck the main waterline servicing Heather Drive. The waterline was clearly marked, and the crew was aware they would be crossing the waterline. The crew was drilling deep underneath the road to prevent causing any road damage but failed to expose the waterline as they got to the other side before crossing it. In doing so the crew punctured the waterline which is defined as a “cross bore”. Armstrong's foreman immediately contacted PA American Water to report the damage. PA American Water responded and repaired their line. Photos were provided showing the damaged water line. 20252450431- Routine ticket placed on 9/2/20255, No Response from- Brightspeed	ARMSTRONG UTILITIES: \$800.00 Section 5(11.2) 1st Offense \$800.00 Brightspeed: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00 XTO Energy Inc/Mountain Gathering LLC: \$250.00 Section 2(4) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		20251902357- Final Design ticket placed on 7/9/2025, No Response from- XTO Energy Inc/Mountain Gathering LLC Violations: *Armstrong Utilities is in violation of section: 5(11.2) – When using trenchless technology, Excavator failed to utilize at a minimum, the best practices published by the Common Ground Alliance. Recommendation: Penalty Applied, and additional fine factor of .6 applied. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. *Brightspeed is in violation of section: 2(5)(v) – Failed to respond to a routine One Call ticket. 20252450431 Recommendation: Penalty Applied. *XTO Energy Inc/Mountain Gathering LLC is in violation of section: 2(4) – Failed to respond to designer’s request for information within 10 business days. 20251902357 Recommendation: Penalty Applied. PUC online Compliance Training is required for the individual(s) responsible for submitting designer’s request	
58605	Facility Owner: Armstrong Cable Contractor/Excavator: Wilson Excavating Project Owner: Peoples Natural Gas Other: AMS Energy	On 9/12/2025 9:00:00 AM at <u>RACHEL DR, CLINTON TWP, BUTLER</u> The incident occurred on 9/12/2025, at 9:00 AM, on Rachel Dr, in Clinton Township, Butler County. A communication line owned by Armstrong Cable was damaged. Armstrong Cable is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/17/2025. An AVR request was sent on 10/17/2025. Their AVR was filed on 10/21/2025 and states, “After talking to our guys on site, the (HFC) Cable was located and marked, the new fiber optic line was not. Excavator hit the unmarked fiber line.” Wilson Excavating is the excavator. Their AVR states, “Wilson Excavating was performing work for Peoples Gas on Rachel Drive in Saxonburg when an unmarked cable line was struck and damaged. They crew hand spotted all marked lines and begun to dig when they struck an unmarked Armstrong Cable line with the excavator. The cable company was notified and made repairs.” Peoples Natural Gas is the project owner, and designer. Their AVR states, “Wilson Excavating was working for Peoples Natural Gas to install new gas lines along Rachel Drive in Saxonburg when an unmarked cable line was struck and damaged. The cable company was notified and repairs were made.”	Armstrong Cable: \$1,000.00 Section 2(5)(i) 2nd Offense \$1,000.00 AMS Energy: \$500.00 Section 2(5)(v) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Images provided show the site, excavation, equipment, damage, and marks. There are no visible marks indicating this line. Ticket #20252471897 New – Excavation – Routine had a response due date of 9/8/2025. AMS Energy did not respond to the ticket. Peoples Natural Gas entered a final response on 9/15/2025 and provided documentation they were in communication with the excavator. Violations: Facility – Armstrong: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility (other) - AMS Energy: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252471897 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58574	Facility Owner: Peoples Natural Gas Contractor/Excavator: GRAHAM AND SONS INC Project Owner: Peoples Natural Gas - Placeholder Other: HARMONY BOROUGH WATER AUTHORITY Other: JACKSON TOWNSHIP BUTLER COUNTY	<u>On 9/16/2025 1:00:00 PM at NICKLE RD, JACKSON TWP, BUTLER</u> The incident occurred on 9/16/2025, at 1:00 PM, on Nickle Rd, in Jackson Twp, Butler County. A gas line owned by Peoples Gas was damaged. Peoples Gas is the facility owner and project owner. Their Alleged Violation Report (AVR) states, “On 9/16/2025, Graham and Sons was working to install sanitary sewer and water along Nickle Road when they struck an unmarked PNG SL. main to curb.” Graham And Sons Inc is the excavator. An AVR has not been filed as of 10/10/2025. An AVR request was sent on 10/10/2025 and they submitted an AVR the same day. Their AVR states, “gas service line was struck along Nickle Road, Jackson Township, Butler County. Peoples Gas did not mark the service line. Other lines were marked except this service line that was struck.” Images submitted show the site, excavation equipment, excavated area, and damaged line. No marks are seen in the area that would indicate the damaged line, though most of the immediate area has disturbed dirt. No mark out photos were provided. Ticket #20252113629 New – Excavation – Routine had a response due date of 8/1/2025. Jackson Township Butler County responded “Clear” on 8/20/2025, and Harmony Borough Water Auth responded “Field Marked” on 8/4/2025. Violations: Facility – Peoples Natural Gas:	Peoples Natural Gas: \$500.00 Section 2(5)(i.1) 2nd Offense \$500.00 HARMONY BOROUGH WATER AUTHORITY: \$250.00 Section 2(5)(v) 1st Offense \$250.00 JACKSON TOWNSHIP BUTLER COUNTY: \$500.00 Section 2(5)(v) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other)-Jackson Township Butler County: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252113629 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other)-Harmony Borough Water Auth: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252113629 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58689	Facility Owner: Municipal Authority of Westmoreland County Contractor/Excavator: Northern Pipeline Construction Project Owner: Columbia Gas Designer: TRC Companies INC Other: North Huntingdon Township Municipal Authority	On 9/17/2025 10:30:00 AM at ARONA ROAD, HEMPFIELD TWP, WESTMORELAND The incident occurred on 9/17/2025, at 10:30 AM, on Arona Road, in Hempfield Twp, Westmoreland County. A water line owned by Westmoreland County Municipal Authority was damaged. Westmoreland County Municipal Authority is the facility owner. Their Alleged Violation Report (AVR) states, “Excavator, NPL was digging to install new gas service lines for Project Owner, Columbia Gas of PA. NPL was moleing under Arona Road to install a new gas service line for 81 Arona Road. This mole and went directly into the side of a Municipal Authority of Westmoreland County (MAWC) unmarked 12" transite water main. NPL contacted MAWC to report the damage. MAWC responded and made the necessary repair. MAWC attended the complex project meeting related to this work in February 2025. Agreement was reached that excavator would place individual tickets as project progressed, and would communicate with MAWC locator as project progressed. The last ticket placed was 20250801998 on 3/21/2025. No further tickets were placed prior to this damage which occurred on 9/17/2025.” Northern Pipeline Construction is the excavator. There AVR was submitted on 10/22/2025 and states, “NPL Construction was working on behalf of Columbia Gas. The crew planned to shoot a mole (pneumatic trenchless bore) under a 6" water mainline. Prior to starting the process, the crew hand dug and spotted the 6" water mainline and other known/located utilities in the area. During the process of shooting of the mole, the mole hit an unmarked/unlocated 12" water mainline. Work was stopped, the area was made safe, and the appropriate personnel were notified immediately. Municipal Authority of Westmoreland County completed the repair.” “The damaged 12" water main was not	Northern Pipeline Construction: \$2,500.00 Section 5(3) 2nd Offense \$1,000.00 Section 5(16) 1st Offense \$1,000.00 Section 5(6)(i) 2nd Offense \$500.00 Columbia Gas: \$1,000.00 Section 6.1(7) 1st Offense \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		located/marked. The utility owner marked the 6" water mainline that was close to it but failed to locate the 12" mainline that was damaged. NPL crew hand dug and spotted the 6" water mainline and there were no signs of another utility within close proximity.” Columbia Gas is the project owner. There AVR was submitted on 10/22/2025 and states, “NPL, working on behalf of Columbia Gas, on an infrastructure replacement project, struck an unmarked 12" water mainline with a pneumatic trenchless bore tool, referred to as a mole. Prior to this trenchless bore, they hand spotted the accurately marked 6" water mainline which they intended to cross. Once spotted, they began to shoot the mole which then resulted in striking the unmarked 12" water main causing an unplanned release of water. Work was stopped and the area was made safe. Once secured, they notified The Municipal Authority of Westmoreland County who responded and made the necessary repairs.” TRC Companies INC is the designer. An AVR has not been filed as of 10/21/2025. The routine tickets submitted for this excavation are for the same area, but covers 2 townships. The total area covered is over a mile, and crosses several intersections. Images submitted show the site, and damage. A yellow mark is the only visible mark in the images. Ticket # 20252603941 New – Excavation– Emergency was entered on 9/17/25 at 2:43 PM. North Huntingdon Township Municipal Authority responded “Field Marked” on 9/18/2025 at 6:54 AM. The damaged occurred in North Huntingdon Township. Tickets included by PA One Call on the Initial Research for other townships were not added to the investigation. Northern Pipeline Construction is overdue on PUC Compliance Training from 7/2025, as of 10/31/2025. Violations: Excavator - Northern Pipeline Construction: Section 5(3) – Excavator failed to preserve mark-outs or request a remark. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. PUC Online Compliance Training is required. Project Owner – Columbia Gas:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement.	
58568	Facility Owner: PEOPLES NATURAL GAS COMPANY LLC Contractor/Excavator: INDEPENDENT ENTERPRISES INC Project Owner: PITTSBURGH WATER Designer: G A I CONSULTANTS INC Other: Verizon PA LLC	<u>On 9/17/2025 11:33:00 AM at 1405 BECKHAM ST., PITTSBURGH CITY, ALLEGHENY</u> PNG penalty and violation have been removed. See attachments. ***** The incident occurred on Wednesday, September 17, 2025, at 1405 Beckham Street, in Pittsburgh City, Allegheny County. Peoples Natural Gas (PNG) line was damaged. PNG stated in their alleged violation report (AVR), on 9/17/2025, Independent Enterprises was working to install water line when they struck an accurately marked PNG SL main to curb. Independent Enterprises and the project owner, Pittsburgh Water stated in their AVR's, while digging a trench for a new water main in front 1405 Beckham Street a gas service line was struck and damaged with an excavator bucket. Initially hand digging took place in the area of the one call mark and a 3-inch white PVC pipe was exposed. This was believed to be a casing for the gas service line because it aligned with the one call mark. Digging continued with the excavator and the gas service line was hit. It was located at a depth of roughly 20" and was 1.5' off the one call mark. Work was stopped and 911 was contacted at 11:15am. The Pittsburgh Fire Department responded to the site at 11:20am. A Peoples Gas rep arrived at 11:24am after and completed a repair to the gas service line at 2:00pm. Photo shows 2 lines, 1 marked and 1 unmarked: "pic1- Independent Enterprises 1405 Beckham Hit Gas Service Line" The day after the damage Independent Enterprises placed Damage Emergency ticket, 20252612506. Remarks-- [PART OF COMPLEX PROJECT NUMBER 10286564. THE GAS LINE WAS OFF MARK BY 18IN. THE DAMAGE OCCURRED YESTERDAY, 911 WAS CALLED AT 1054, AND THE DAMAGE HAS BEEN DEALT WITH BY PEOPLES.] 20251250961- Complex Project Meeting ticket placed on 5/5/2025, No Response from- Verizon PA LLC Violations: *Peoples Natural Gas Company is in violation of section: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Recommendation: Penalty Applied *Independent Enterprises is in violation of section:	PEOPLES NATURAL GAS COMPANY LLC: \$0.00 INDEPENDENT ENTERPRISES INC: \$1,000.00 Section 5(9) 1st Offense \$1,000.00 Verizon PA LLC: \$2,000.00 Section 2(5)(viii) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. 20252612506 Recommendation: Penalty Applied. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. *Verizon PA LLC is in violation of section: 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project. 20251250961 Recommendation: Penalty Applied	
58641	Facility Owner: Peoples Natural Gas Contractor/Excavator: A Folino Construction Project Owner: Pittsburgh Water Designer: Johnson, Mirmiran & Thompson Other: Comcast	On 9/19/2025 11:45:00 AM at S 19TH STREET, PITTSBURGH CITY, ALLEGHENY The incident occurred on 9/19/2025, at 11:45 AM, at 48 S 19th Street, in Pittsburgh City, Allegheny County. A gas line owned by Peoples Natural Gas was damaged. Peoples Natural Gas is the facility owner. Their Alleged Violation Report (AVR) states, “A Folino working for Pittsburgh Water and Sewer, struck and damaged a Peoples Gas service line. The last time Folino placed a One Call request for this area was in June of 2024; it was an UPDATE NO REMARKS ticket. Per the Peoples Gas responder, no markings were visible on the street.” A Folino is the excavator. Their AVR states, “ A. Folino Construction was digging in front of 50 S 19th St to install new sewer service lines when we hit a mismarked gas service line. 911 was called and a damage ticket was made through 811. Peoples Gas responded and claimed the line as theirs. Peoples Gas had a crew come out and make the repairs.” A Folino listed Ticket # 20251742502 New – Excavation – Routine with their AVR. The site for this ticket is south of the damage location, and does not include where the excavation occurred. Pittsburgh Water is the project owner. An AVR has not been filed as of 10/20/2025, and an AVR request letter was sent on the same day. All other stakeholder submitted an AVR by the due date. Pittsburgh Water’s AVR was submitted on 10/21/2025 and states, “While removing deep curb in front of the house 50S.19th Curb pinched gas line and created a pinhole. I was at a site meeting at the time of the initial event and can't report as an eyewitness. Foreman called 911, Fire dept arrived 5 min later, repair crew arrived and hr later then finished the repair at 12:41pm. Hit kit provided by people's gas shows the market and the hit were less than 3' apart” Johnson Mirmiran And Thompson J M T is the designer. Their AVR adds the following information to the investigation, “Lines were shown on the bid documents.” JMT submitted documents showing the line that was damaged was marked on the drawings. The damaged occurred at 48th South 19th Street as indicated on the Emergency-Damage ticket. No active PA One Call tickets for A Folino could be located by PA	A Folino Construction: \$2,000.00 Section 5(2.1) 2nd Offense \$1,500.00 Section 5(6)(i) 2nd Offense \$500.00 Pittsburgh Water: \$2,000.00 Section 6.1(7) 3rd Offense \$2,000.00 Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		One Call for this site. Mechanized equipment is seen at the excavation. Ticket #20252620444 New – Damage – Emergency was entered on 9/19/25 at 8:08 AM. Comcast responded “Clear” on 9/23/2025. This case is related by tickets to the following cases: 050269, 052547 Violations: Excavator – A Folino: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Project Owner - Pittsburg Water : Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility(other) – Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252620444 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58833	Facility Owner: Homeowner Contractor/Excavator: North End Electric Project Owner: Aqua America Other: Comcast Other: Verizon	<u>On 9/23/2025 9:15:00 AM at 750 WILLARD RD, JEFFERSON TWP, LACKAWANNA</u> The incident occurred on 9/23/2025, at 9:15 AM, on 750 Willard Rd, in Jefferson Twp, Lackawanna County. A communication line owned by the homeowner was damaged. Verizon is a facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/20/2025, and an AVR request was the sent the same day. An AVR was submitted on 10/23/2025 which states, “This does not appear to be a Verizon Line. Verizon's locator completed the Routine ticket "Cleared in field No Facilities". The local manager reviewed this case and did not find any damage report Verizon's records. I also searched for a customer reported ticket and did not find any reports of a damaged customer line. For good measure I checked the OMEGA facility and google maps as a cross reference (see attached). The OMEGA map displays cables that run ups along 3rd Ave -cable 502 counts 351-400- which end on Willard Ave. However, there is nothing that indicates we have a cable directly in front or directly	Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00 Verizon: \$2,500.00 Section 2(5)(vii) Subsequent \$2,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		across from the address in the original locate request. *** Update:; Based on our conversation, the first locate was marked as clear because there were no underground cables in the requested mark-out area. The second locate was a notification regarding a cable hit. However, when the technician arrived, he determined it was a service loop feeding a customer, not a main cable. He verified that the customer's service was still active before responding to the ticket.” Verizon verified their statement that this is a customer owned line. North End Electric is the excavator. Their AVR states, “-Myers and Northend and Aqua meet with property owner at Jeferson Well #1 to discuss proposed work. Due to the nature of the situation, all parties agreed to start work ASAP (9/23). -North End called in an emergency PA 1 call in order to get mark out within 12 hrs for next shift. -When we arrived onsite, water lines were marked, and electric from street to meter along with well to panel. That was it, Verizon stated “CLEAR NO CONFLICTS”. They were even out in the morning. -North end started digging for the new enclosure pad and discovered an unmarked, unidentified casing cable, and barely nicked it. We knew immediately it was some sort of com line. Work was stoped and north end reached out to 811 and verzion to get someone out to site immediately to verify. -Verizon came out and stated “oh we didn’t know that was ours”... They checked the box at the street, confirmed it was indeed there’s, and then traced and marked out the rest of the line to make sure it wasn’t gonna be a further issue. -Northend then continued work.” Aqua Pennsylvania Inc is the project owner. Their AVR states, “Aqua Contractor North End Electric working for Allen Myers and Aqua, met with property owner at Jefferson Well #1 to discuss proposed work. Due to the nature of the situation, all parties agreed to start work ASAP (9/23). North End placed a Emergency PA1 ticket to get mark outs within 12 hours for next shift. When crew arrived onsite, water lines were marked and electric from street to meter along with well to panel. There were no other marks - Verizon responded as Clear No Conflicts. Verizon locator was out that morning. North End started digging for new enclosure pad and discovered an unmarked, unidentified casing cable and barely nicked it. Crew knew this was some type of communication line. Work was stopped and North End notified 811 and Verizon to have someone respond to the site immediately to verify. Verizon responded and stated "oh we didn't know that was ours". They checked the box at the street and confirmed it was indeed their line and traced and marked out the rest of the line to make sure it wasn't going to be a future issue. North End continued work.” Ticket #20252653039 New – Excavation– Emergency was entered on 9/22/25 at 1:55 PM with a dig date calculated at 9/22/25, 11:59 PM. Verizon responded “Clear” on 9/23/2025 at 7:49AM.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Ticket # 20252662449 New – Damage – Emergency was entered on 9/23/25 at 12:55 PM. Comcast responded “Clear” on 10/17/2025. Violations: Facility (other)– Verizon: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252653039 - PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other)-Comcast Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252662449 - PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58698	Contractor/Excavator: Wilson Excavating Project Owner: Pennsylvania American Water (PAWC) Other: COLUMBIA GAS OF PA INC_Central	On 9/23/2025 1:45:00 PM at CLIMAX ST, PITTSBURGH CITY, ALLEGHENY Wilson violation removed Columbia Gas provided documentation via email - 2(5)(i) violation withdrawn. ***** The incident occurred on 9/23/2025, at 1:45 PM, on Climax St, in Pittsburgh City, Allegheny County. A gas line owned by Columbia Gas was damaged. Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Wilson Excavating working on behalf of PA American Water for a replacement project, damaged a 1" plastic company side service line. Line was accurately marked. 911 and Columbia Gas was notified. Service tech and plant crew responded and made repairs. All safety checks were completed.” Wilson Excavating is the excavator. Their AVR states, “Wilson Excavating was performing work for PA American Water Company on Climax Street in Pittsburgh when a Columbia Gas line was struck. The crew had a "Vac to Locate" order for the job and located a water line and gas line near the marks. The lines were exposed and protected as work continued. The Operator used an excavator about 6" from the exposed water line to remove some rock and struck another gas service that was close by. This second gas line was not expected as only one gas line was marked and previously found from the vac excavation. The facility owner was notified and 911 was called.” Pennsylvania American Water is the project owner and designer. An AVR has not been filed as of 10/20/2025 and an AVR request was sent the same day. They filed an AVR on 10/21/2025 that states, “Wilson while digging to install water main hit and damaged an unmarked gas service within the tolerance zone of the marked gas service. The marked service was vac'd and	Wilson Excavating: \$0.00 COLUMBIA GAS OF PA INC_Central: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		exposed and Wilson used due care to proceed when they encountered the unmarked. Wilson had emailed PAWC to the incorrect email address therefore this AVR was not able to be filed in a timely manner.” Images submitted show the site, marks, excavation, and damaged line. No mark out photos from before excavation began were provided. A hit kit is used to show the damaged line is within the tolerance zone of the yellow mark. There is another gas line outside of the tolerance zone that was previously exposed by Wilson Excavating, but there was no report to PA One Call as unmarked or incorrectly marked. Ticket #20252521023 New – Excavation –Routine had a response due date of 9/14/2025. PITTSBURGH WATER & SEWER responded “Clear” on 9/9/2025 and “Field Marked” on 9/30/2025. The excavator did not call in an incorrectly marked line after exposing a gas line outside of the tolerance zone. A second gas line, which was then damaged, was marked correctly but was not exposed, and was then later damaged. Violations: Facility – Columbia Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator – Wilson Excavating: Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.	
58674	Facility Owner: Veolia Water PA Inc Contractor/Excavator: DOLI Construction Project Owner: Lower Paxton Township Authority Designer: HRG INC Other: Comcast	<u>On 9/23/2025 2:00:00 PM at LANCASTER AVE., LOWER PAXTON TWP, DAUPHIN</u> The incident occurred on 9/23/2025, at 2:00 PM, on Lancaster Ave., in Lower Paxton Twp, Dauphin County. A water line owned by Veolia was damaged. Veolia is the facility owner. An Alleged Violation Report (AVR) was not filed as of 10/17/2025 and an AVR request was sent the same day. An AVR was submitted on 10/21/2025 and states, “we had potholed the main for doli and they still hit the main”. DOLI Construction is the excavator. Their AVR states, “Crew was excavating to replace a sanitary sewer main when they pulled a rock into a marked water main. The water main is plastic so the rock caused a crack in the pipe.”	DOLI Construction: \$1,000.00 Section 5(6)(ii) 2nd Offense \$1,000.00 Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Lower Paxton Township Authority is the project owner. Their AVR states, “.Doli's crew was excavating to replace a sanitary sewer main when they pulled a rock into a marked plastic water main causing a crack in the pipe.” HRG Inc is the designer. Their AVR states the same summary as the excavator’s AVR. The images provided show a pit that was excavated using an excavator’s bucket as indicated by the bucket marks in the sidewalls of the pit. There is a damaged water line shown and is leaking water. No photos were provided showing marks. Statements from the stakeholders indicates the excavator caused the damage while using mechanized equipment in the tolerance zone and not providing protection for known lines. Ticket # 20252604527 New – Excavation – Routine had a response due date of 9/19/2025. Comcast responded “Clear” on 10/3/2025. This case is related to the following cases by design and complex project tickets: 052101, 052187, 052200, 052431, 054080, 054983, 055459, 056426, 056684, 057203, 057951 Violations: Excavator – DOLI Construction: Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility(other) – Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket # 20252604527 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
58814	Facility Owner: Franklin Township Muncpal Sanitary Authority Contractor/Excavator: BRIAN SCHMUCKER GENERAL CONTRACTOR Project Owner: WEST PENN POWER Other: Comcast	On 9/29/2025 6:35:00 AM at 47 Hones Road, <u>MURRYSVILLE MUNIC. WESTMORELAND</u> The incident occurred on 9/29/2025, at 6:35 AM, on 47 Hones Road, in Murrys ville Munic, Westmoreland County. This report is in reference to an emergency ticket. No damage occurred. Franklin Township Muni Sanitary Auth submitted an Alleged Violation Report (AVR). Their AVR states, “Brian Schmucker General Contracting provided Onecall with misleading information to submit a Emergency one call. Doing a bore under a road for West Penn Power for a new electric line does not constitute an emergency.”	BRIAN SCHMUCKER GENERAL CONTRACTOR: \$1,000.00 Section 5(9) 1st Offense \$1,000.00 Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Brian Schmucker General Contractor is the excavator. An AVR has not been filed as of 10/23/2025. West Penn Power is the project owner. An AVR has not been filed as of 10/23/2025. Ticket #20252720064 New – Excavation– Emergency was entered on 9/29/25 at 6:34 AM to “INSTL NEW ELEC LINE”. Comcast responded “Field Marked” on 10/2/2025. "Emergency" means a sudden or unforeseen occurrence involving a clear and immediate danger to life, property or the environment, including, but not limited to, serious breaks or defects in a facility owner's lines. Violations: Excavator - Brian Schmucker General Contractor: Section 5(9) – Emergency notification does not meet the requirements of “emergency” as defined in Section 1 – Excavator Ticket. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Facility(other) - Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
59085	Facility Owner: Peoples Gas Contractor/Excavator: Mele and Mele and Sons Project Owner: Pittsburgh Water & Sewer Authority Designer: MS CONSULTANTS Other: JOHNSON MIRMIRAN AND THOMPSON J M T Other: VERIZON BUSINESS FORMERLY MCI	<u>On 10/6/2025 8:00:00 AM at 4551 COMRIE WAY, PITTSBURGH CITY, ALLEGHENY</u> Peoples Gas accepts. ***** The incident occurred on October 6th, 2025, at 8:00 AM, at 4551 Comrie Way, in Pittsburgh City, Allegheny County. A gas line owned by Peoples Gas was damaged. 911 was not called. Peoples Gas, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Mele and Mele and Sons struck and damaged the Peoples Gas service to 4559 Carrol St working on a One Call request from May.” Photos were submitted. Mele and Mele and Sons, the excavator, submitted an AVR. Their AVR states, “During excavation operations on a 15" Sewer line, crews caught a 1" gas service which caused damage to the line. Mele crews contacted Peoples Gas, and their emergency response team cinched the line till a repair crew showed up. The damage happened at 0800 AM, and people's gas arrived on site around 0845 am to make the repair.”	Peoples Gas: \$250.00 Section 2(5)(v) 1st Offense \$250.00 Mele and Mele and Sons: \$2,000.00 Section 5(4) 2nd Offense \$1,000.00 Section 5(8) 1st Offense \$1,000.00 VERIZON BUSINESS FORMERLY MCI: \$250.00 Section 2(5)(v) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Pittsburgh Water & Sewer Authority, the project owner, submitted an AVR. Their AVR states, " Mele hit an accurate marked Peoples Gas service line." Photos were submitted. MS Consultants, the designer, submitted an AVR. Their AVR states, " During excavation operations on a 15-inch sewer line, contractor (Mele & Mele & Sons) caught a 1" gas service line which caused damage to the line. Mele & Mele & Sons contacted Peoples Gas and their emergency response team cinched the line until a repair crew arrived. The damage occurred at 8:00 AM and Peoples Gas made the repair at 8:45 AM." Mele and Mele and Sons and Peoples Gas noted on their AVRs that 911 was not called. The submitted photos show the line was properly marked and damaged within the tolerance zone. Routine ticket 20252391199 had a response due date of 09/07/2025. - Verizon Business responded on 09/08/2025. - Peoples Gas responded on 09/08/2025. Violations: Mele and Mele and Sons- - Section 5(4) – Excavator failed to exercise due care and employ prudent excavation techniques. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. Recommendation: The penalty is applied. PUC compliance training education is required. Verizon Business= - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252391199. Recommendation: The penalty is applied. PUC compliance training education is required. Peoples Gas- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252391199. Recommendation: The penalty is applied. PUC compliance training education is required.	
59179	Facility Owner: PECO Contractor/Excavator: BRUBACHER EXCAVATING INC Project Owner: Pennsylvania American Water (PAWC) Designer: Pennsylvania American Water (PAWC) - Placeholder Other: Verizon	<u>On 10/9/2025 10:45:00 AM at S WAKEFIELD RD, WEST NORRITON TWP, MONTGOMERY</u> West Norriton Township provided additional information- 2(5)(vii) reduced from \$1000 to a warning of \$0 ***** The incident occurred on 10/9/2025, at 10:45 AM, on S Wakefield Rd, in West Norriton Twp, Montgomery County. A gas line owned by PECO was damaged.	PECO: \$2,000.00 Section 2(5)(i) Subsequent \$2,000.00 Verizon: \$4,000.00 Section 2(5)(vii) Subsequent \$2,500.00 Section 2(5)(viii) 3rd Offense \$1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Other: West Norriton Township	PECO is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/30/2025 and an AVR request was sent the same day. PECO submitted their AVR which states, “Brubacher working for the water company struck a mis-marked water service.” “The record for the house at 1825 was an old outdated record, the measurements were pulled from a curb line that is no longer there, which made the measurements off by about 5ft.” Brubacher Excavating Inc is the excavator. Their AVR states, “While excavating the trench for new water main installation on N Wakefield project, the crew encountered an unmarked gas line. A 1/2" diameter steel pipe with plastic inside was found at 2'- 8" deep. The excavation was in the street at 1825 W Main St (across from S Wakefield). The work was being performed for PAWC. Original Ticket #2025 258 0250 and the damage ticket #2025 282 1435. 911 was contacted.” Pennsylvania American Water is the project owner and designer. Their AVR states, “While excavating the trench for new water main installation on N Wakefield project, the crew encountered an unmarked gas line. A 1/4 inch plastic was discovered in the area of the mark. A 1" diameter steel pipe with plastic inside was found at 2'- 8" deep approximately 3 feet from the mark. The excavation was in the street at 1825 W Main St (across from S Wakefield). Original Ticket #2025258 0250 and the damage ticket #2025 282 1435. 911 was contacted. Fire, police and PECO responded PECO indicated that this was a marking issue and not Brubacher.” Images submitted show the site, marks and damage. The line that was damaged was 27” from the mark as shown using a hit kit. Ticket #20252821435 New – Damage – Emergency was entered on 10/9/25 at 10:55 AM. West Norriton Township responded “Field Marked” on 10/14/2025. PECO responded “Clear” on 10/9/2025 at 3:16 PM. Verizon responded “Insufficient Information” on 10/27/2025. Ticket #20252242768 New – Excavation– Complex Project was on 8/21/2025 – Verizon did not respond through PA One Call till 9/15/20205 with “Insufficient Information”. Violations: Facility – PECO: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) – West Norriton Township: Section 2(5)(vii) – Failed to respond to an emergency	West Norriton Township: \$0.00 Section 2(5)(vii) 1st Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		notification as soon as practicable following notification. Ticket #20252821435 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) – Verizon: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252821435 Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). Ticket #20252242768 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
59450	Contractor/Excavator: NICKETT LANDSCAPING Project Owner: Homeowner Other: Verizon	<u>On 10/17/2025 12:00:00 AM at 3765 LANCASTER DR, BUCKINGHAM TWP, BUCKS</u> The incident occurred on 10/17/2025, at 12:00 AM, on 3765 Lancaster Dr, in Buckingham Twp, Bucks County. This incident involves ticket responses only. No damage occurred. Nickett Landscaping is the excavator. Their AVR states, “Verizon has not responded once again past lawful date and we are pending response to start work”. The homeowner is the project owner. Routine Ticket 20252863116 had a response due date of 10-16-2025. A renotify was entered on 10/17/2025 at 11:22AM. Verizon responded Field Marked on 10/17/2025 at 12:31PM to the renotify ticket but did not respond to the routine ticket by the response due date. Violations: Facility(other) – Verizon: Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket #20252863116 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00

Full Session

Case Number	Stakeholders	Summary	Violations & Recommendation
59314	Facility Owner: Duquesne Light Company Contractor/Excavator: VANTAGE CORPORATION Project Owner: Pittsburgh Regional Transit Designer: AECOM Other: LUMEN formerly level 3	<u>On 6/10/2025 10:24:00 AM at FORBES AVE, PITTSBURGH CITY, ALLEGHENY</u> 2026 February Damage Prevention Committee - the DPC voted on Vantage Corporation's violations: 5(2.1) - Remove 5(6)(i) - Remove 5(16) - Keep violation and education, reduce penalty from \$1000 to \$0. ***** Duquesne Light Company - Provided details that they contacted the excavator on the Emergency ticket, even	Duquesne Light Company: \$1,750.00 Section 2(5)(vii) 1st Offense \$0.00 Section 2(5)(v.2) 1st Offense \$250.00 Section 2(10) 2nd Offense \$1,500.00 VANTAGE

Case Number	Stakeholders	Summary	Violations & Recommendation
		though they did not enter a final response to the ticket. Violation reduced from \$1000 to a warning of \$0. Vantage Corp disputing ***** After the case was submit, PITTSBURGH REGIONAL TRANSIT entered an AVR that states, "On 6/10/25 at approximately 9:41 AM, a Vantage corporations employee damaged an electrical line that was unmarked. During traffic signal foundation at the intersection of Forbes Ave and the Birmingham Bridge on off ramp when an unmarked electrical duct bank was hit about 4.5 ft deep. 811 was called prior to excavation. Due to it being an unknown utility, the line was not marked, and it was not shown on the prints. There was a service outage that was corrected by Duquesne Light Company. No injuries occurred in result of this strike." No images or documents were included. ***** After the case was submit, and AVR by CDR Maguire was entered that states, "On 6/10/25 at approximately 9:41 AM, a Vantage corporations employee damaged an electrical line that was unmarked. During traffic signal foundation at the intersection of Forbes Ave and the Birmingham Bridge on off ramp when an unmarked electrical duct bank was hit about 4.5 ft deep. 811 was called prior to excavation. Due to it being an unknown utility, the line was not marked, and it was not shown on the prints. There was a service outage that was corrected by Duquesne Light Company. No injuries occurred in result of this strike". ***** The incident occurred on 6/10/2025, at 10:24 AM, on Forbes Ave, in Pittsburgh City, Allegheny County. An electric line owned by Duquesne Light was damaged. An emergency ticket was entered for this incident. Duquesne Light is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 11/25/2025 and an AVR request was sent. AVR was filed on 12/16/2025, which is 188 days after the incident, that states, "Vantage Corporation, working for Pittsburgh Regional Transit, were excavating to install light poles when they struck and damaged an unmarked underground electrical conduit and cable belonging to Duquesne Light Company. The line was not marked due to the dig site being outside the bounds of Vantage Corp.'s One Call ticket. Their ticket clearly states work will be done on Forbes Ave. between Moultrie St and Brady St. whereas the line that was damaged is further north beyond Brady St., heading towards Oakland. The dig site should have been between the ramp to Birmingham Bridge and Brady St along Forbes Ave. A Damage One Call ticket was placed and a phone call to DLC was made by the excavator. Duquesne Light Overhead Supervisors, Underground Supervisors, Troubleshooters, and Locator responded to the site to assess the damage. DLC Locator advised the excavator to place a new One Call ticket with the correct work site information, which was placed 12 June 2025. Duquesne	CORPORATION: \$0.00 Section 5(16) 1st Offense \$0.00 Pittsburgh Regional Transit: \$0.00 Section 6.1(7) 1st Offense \$0.00 LUMEN formerly level 3: \$1,500.00 Section 2(5)(v) 3rd Offense \$1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Light Locators responded to the ticket and marked our facilities accordingly.-----questions attached to the letter requesting our AVR----- 1.) Did the excavator call 911 or notify you as the facility owner?-- yes, both happened. 911 was called and EMS responded to the scene according to the Damage One Call ticket (20251611620) and they called Duquesne Light Company to report the damage. 2.) Was the line marked within the tolerance zone?--it was not marked. 3.) Has this excavator hit two or more of your lines in a 6-month period?-- they have not.” Vantage Corporation is the excavator. Their AVR was submitted on 10/15/2025, which is 127 days after the incident, and states, “ON JUNE 10TH 2025 VANTAGE CORP. WAS WORKING UNDER A LEGAL ONE CALL TICKET AND HIT A DUQUESNE LIGHT LINE. LEGAL START DATE WAS JUNE 5,2025 WORK WAS STARTED WITHIN LEGAL TIMEFRAME. DUQUESNE LIGHT DID NOT MARK THEIR LINES, RED MARKINGS WERE FROM CITY OF PITTSBURGH, THERE WAS NO COMMUNICATION FROM FACILITY OWNER TO VANTAGE CORP. TICKET STATED "FIELD MARKED - CONFLICT. LINES NEARBY. DIRECT CONTACT TO FOLLOW BY FACILITY OWNER" OTHER FACILITIES WERE CLEARLY MARKED AND UNAFFECTED. DUQUESNE LIGHT CAME OUT WITH EMERGENCY ONE CALL AND MADE VANTAGE CORP. AWARE OF AN UNMARKED ELECTRICAL MANHOLE AFTER DAMAGE TOOK PLACE.” Pittsburgh Regional Transit is the project owner. An AVR has not been filed as of 12/18/2025. Due to the late filing of AVRs by the Excavator and Facility, an AVR request was not sent the Project Owner due to the time limits of Act 127 of 2024. Ticket #20251530670 New – Excavation – Routine had a response due date of 6/4/2025. This ticket indicates in “Location Information”, “ WORKING ON FORBES AVE BETWEEN MOUTRIE ST AND BRADY ST. IN FRONT OF DUQUESNE LIGHT SUB STATION AND UNDER BIRMINGHAM BRIDGE”. Damage did not occur within the area described in the ticket. Excavator was operating outside of the ticket when damage occurred. Duquesne Light also did not enter a final response to the ticket. Duquesne Light responded “Conflict.” as their only response. Lumen responded “Clear” on 6/12/2025 as their only response. Ticket # 20251611620 New – Damage – Emergency was entered on 6/10/25 at 10:24 AM. Duquesne Light responded “Conflict.” as their only response. Ticket # 20251632287 New – Excavation – Routine was entered on 6/12/2025, after the damaged occurred, and included the area where the damage occurred and stated in the “Location Information”, “WORKING ON	

Case Number	Stakeholders	Summary	Violations & Recommendation
		FORBES AVE UNDER THE BIRMINGHAM BRIDGE FROM THE BRADY ST INTERSECTION TO THE ON/OFF RAMP” Violations: Facility - Duquesne Light: Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20251611620 Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20251530670 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Excavator - Vantage Corporation: Section 5(2.1) – Excavator failed to submit a location request to One Call within the correct timeframe. Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements. Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Project Owner - Pittsburgh Regional Transit: Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. This violation is reduced from \$1000 to a warning of \$0. PUC online Compliance Training is required for the person responsible for submitting AVRs, or their replacement. Facility(other) – Lumen: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20251530670 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
57379	Facility Owner: Comcast Contractor/Excavator: Wicked Bull Enterprises	On 7/23/2025 12:00:00 PM at 1632 MANOR BOULEVARD, MANOR TWP, LANCASTER On	Comcast: \$4,000.00 Section 2(5)(i) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
	Project Owner: Shentel Communications LLC. Designer: Shentel Communications LLC (Placeholder) Other: Met Ed/ Frist Energy Other: PPL	02/10/2026: The Damage Prevention Committee (DPC) voted to keep the violation and penalty as is for Met-Ed. **** Met-Ed disputing 2(5)(v) Comcast accepts. **** The incident occurred on July 23rd, 2025, at 12:00 PM, at 1632 Manor Boulevard, in Manor Township, Lancaster County. A cable tv line owned by Comcast was damaged. Comcast is the facility owner. An Alleged Violation Report (AVR) has not been filed as of 10/24/2025. Wicked Bull Enterprises is the excavator. An AVR has not been filed as of 10/24/2025. Shentel Communications LLC, the project owner and designer, submitted an AVR. Their AVR states, "The primary reason the damage occurred is due to the Comcast locator's positive response of 001- Clear no facilities or facilities not involved based on ticket information on ticket 20251830540. Update tickets 20252022352 & 20252022358 were both had a positive response of 001- Clear no facilities or facilities not involved based on ticket information." "The damage occurred while the excavator was digging a missile pit struck and damaged the unmarked comcast drop conduit. It did not appear that the drop inside of the conduit was damaged." The submitted photos show that Comcast did not mark their line. They responded "Clear" to routine ticket 0252030929. The orange paint that can be seen in photos is for Verizon PA as they wrote VZPA next to their paint marking. The type of equipment listed on the routine ticket was drill and missile. Shentel Communications LLC's AVR noted that the damage occurred while the excavator was digging a missile pit. The lawful start dates for the routine ticket 20252030929 were 07/25/2025 thru 08/05/2025. The damage occurred on 7/23/2025, prior to the lawful start date. Routine ticket 20252030929 had a response due date of 07/24/2025. - Met Ed/ First Energy did not respond to this ticket until 07/25/2025. - PPL did not respond to this ticket until 07/25/2025. - Comcast timely responded, "CLEAR. NO FACILITIES OR FACIL NOT INVOLVED" on 07/22/2025 but had lines in the area, including damaged line, that should have been marked.	Section 2(10) 3rd Offense \$2,000.00 Wicked Bull Enterprises: \$2,000.00 Section 5(16) 1st Offense \$1,000.00 Section 1.1 1st Offense \$1,000.00 Met Ed/ Frist Energy: \$500.00 Section 2(5)(v) 2nd offense \$500.00 PPL: \$750.00 Section 2(5)(v) 3rd offense \$750.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		This case is related to case 057378. Violations: Comcast- - Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket 20252030929. - Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. Recommendation: The penalty is applied. PUC compliance training education was recently completed. Wicked Bull Enterprises- - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. - Section 1.1 – Excavator did not begin within legal timeframe. Ticket 20252030929. Recommendation: The penalty is applied. PUC compliance training education is required. Met Ed/ First Energy- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252030929. Recommendation: The penalty is applied. PUC compliance training education was recently completed. PPL- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Ticket 20252030929. Recommendation: The penalty is applied. PUC compliance training education was recently completed.	
57253	Facility Owner: Carnegie Mellon University (Placeholder) Contractor/Excavator: Eisler Landscapes Inc. Project Owner: Carnegie Mellon University Other: Peoples Gas	On 7/31/2025 11:44:00 AM at SKIBO DRIVE, PITTSBURGH CITY, ALLEGHENY On 02/10/2026: The Damage Prevention Committee (DPC) voted the following for Eisler Landscapes Inc.: 5(13)- Remove the violation and penalty. 5(6)(i)- Keep the violation, penalty, and education requirement. 5(16)- Remove the violation and penalty. ***** Eisler Landscapes Inc. is disputing. The violation of Section 5(8) was withdrawn. Documentation showing 911 was called was submitted. ***** The incident occurred on July 31st, 2025, at 11:44 AM, on Skibo Drive, in Pittsburgh City, Allegheny County.	Eisler Landscapes Inc.: \$250.00 Section 5(6)(i) 1st Offense \$250.00 Carnegie Mellon University: \$250.00 Section 6.1(7) 1st Offense \$0.00 Section 2(1) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		A Carnegie Mellon University (customer owned) gas line was damaged. Peoples Gas submitted an Alleged Violation Report (AVR). Their AVR states, “Eisler Landscapes Inc working for Carnegie Mellon University struck and damaged the customer side gas service line while using mechanized equipment with clear evidence of underground utilities in the work area. The description of the One Call dig area and type of work are remove and replace curbing on Skibo Dr. The work area was outlined in white and Peoples Gas marked the corresponding work area. This damage was approximately 200' away from Skibo Dr.” Photos were submitted. Eisler Landscapes Inc. is the excavator. An AVR has not been filed as of 10/21/2025. Carnegie Mellon University is the facility owner and project owner. An AVR has not been filed as of 10/21/2025. Carnegie Mellon University is not a registered member of One Call within Pittsburgh City, Ward 14. Peoples Gas’ AVR did not indicate if 911 was called. The routine ticket 20251272906 noted the work site as, “Skibo Drive. The location reported on the ticket was: Carnegie Mellon University. Working on Skibo Dr. for the curbing work. All areas marked in white.” The damage occurred on Margaret Morrison Street, which was outside out the scope of the ticket. Violations: Eisler Landscapes Inc.- - Section 5(13) – Excavator changed the location, scope, or duration of a proposed excavation without notifying the One call System. (DPC voted to remove this violation.) - Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. - Section 5(8) – Excavator failed to immediately notify 911 and the facility owner when damage resulted in the escape of any flammable, toxic or corrosive gas or liquid which endangers life, health, or property. - Withdrawn. - Section 5(16) – Excavator Failed to submit an Alleged Violation Report within 30 days of striking a line or if the excavator believes a violation of this act has been committed in association with excavation or demolition work. (DPC voted to remove this violation.) Recommendation: The penalty is applied. PUC compliance training education is required. Carnegie Mellon University-	

Case Number	Stakeholders	Summary	Violations & Recommendation
		- Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. - This is a warning. No penalty applied for this violation. - Section 2(1) – Facility owner is not a member of One Call. Recommendation: Penalty is applied. Both the project owner and facility owner, PUC compliance training education are required.	
57215	Facility Owner: AQUA PA Contractor/Excavator: PACT CONSTRUCTION Project Owner: BUCKS COUNTY WATER SEWER AUTHORITY Designer: JONES ENGINEERING AND ASSOCIATES Other: Comcast Other: PECO Other: SPRINGFIELD TOWNSHIP OF MONTGOMERY CO	On 8/5/2025 11:00:00 AM at SOUTHAMPTON AVENUE, SPRINGFIELD TWP, MONTGOMERY On 02/10/2026: The Damage Prevention Committee (DPC) voted on SPRINGFIELD TOWNSHIP OF MONTGOMERY CO. violation. The DPC voted to accept the violation and penalty as is and add an additional \$250.00 penalty for not attending the DPC meeting. SPRINGFIELD TOWNSHIP OF MONTGOMERY CO. was not in attendance at the DPC meeting. ***** SPRINGFIELD TOWNSHIP OF MONTGOMERY CO is disputing. Education requirement removed since they recently completed facility owner education on 12/17/2025. BUCKS COUNTY WATER SEWER AUTHORITY submitted additional information. Violation of 6.1(7) was withdrawn. PECO accepts ***** The incident occurred on August 5th, 2025, at 11:00 AM, on Southampton Avenue, in Springfield Township, Montgomery County. A water line owned by Aqua PA was damaged. Aqua PA, the facility owner, submitted an Alleged Violation Report (AVR). Their AVR states, “Excavator failed to protect the water service, shoring not in place, trench caved in striking 1" water service, pulling the corp out of the main.” Pact Construction, the excavator, submitted an AVR. Their AVR states, “During the course of sanitary sewer installation and while advancing trench shoring systems, a trench sidewall shifted and pulled a water service out of the water main. Water service was exposed in its entirety in advance of the work with no issues to report.” Bucks County Water Sewer Authority is the project owner. An AVR has not been filed as of 10/23/2025. Jones Engineering and Associates, the designer. An AVR has not been filed as of 10/23/2025. The submitted photos show the water line was accurately marked. The line was completely uncovered when the damage occurred within the tolerance zone.	PACT CONSTRUCTION: \$500.00 Section 5(6)(ii) 1st Offense \$500.00 BUCKS COUNTY WATER SEWER AUTHORITY: \$0.00 Comcast: \$3,000.00 Section 2(5)(v) Subsequent \$1,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00 PECO: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00 SPRINGFIELD TOWNSHIP OF MONTGOMERY CO: \$1,250.00 Section 2(5)(vii) 1st Offense \$1,250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Routine ticket 20251952038 had a response due date of 07/20/2025. - Comcast replied on 07/21/2025. - PECO replied on 07/21/2025. Emergency ticket 20252172098 had a response due date of 08/05/2025. - Springfield Township of Montgomery Co. responded on 08/07/2025. - Comcast responded on 08/29/2025. This case is related to case 056169. Violations: Pact Construction- - Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site Recommendation: The penalty is applied. PUC compliance training education is required. Bucks County Water Sewer Authority- - Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. - Withdrawn. Recommendation: The penalty is applied. PUC compliance training education is required. Springfield Township of Montgomery Co.- - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252172098. Recommendation: The penalty is applied. PUC compliance training education was recently completed. Comcast- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20251952038. - Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Emergency ticket 20252172098. Recommendation: The penalty is applied. PUC compliance training education was recently completed. PECO- - Section 2(5)(v) – Failed to respond to a routine One Call ticket within the required amount of time. Routine ticket 20251952038. Recommendation: The penalty is applied. PUC compliance training education was recently completed.	
57702	Contractor/Excavator: Smith Construction & Son LLC Project Owner: Aqua Other: Breezeline Other: PPL	<u>On 8/8/2025 7:00:00 PM at LAKEVIEW DR, RICE TWP, LUZERNE</u> 2026 February Damage Prevention Committee - the DPC voted to remove Aqua's penalty. **** Aqua disputing 2(5)(i) ***** The incident occurred on 8/8/2025, at 7:00 PM, on Lakeview Dr, in Rice Twp, Luzerne County.	Aqua: \$0.00 Breezeline: \$1,500.00 Section 2(5)(vii) 2nd Offense \$1,500.00 PPL: \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		An unknown line was damaged. PPL submitted an Alleged Violation Report (AVR) that states, “PPL was notified of a possible damage to our facility; A crew was sent to the site and was unsure if the line was owned by PPL. The job was sent back to the underground crew and then to our design department, After our investigation it was determined that the line does not belong to PPL. But an AVR was filed by the contractor. PPL will submit our own AVR.” Smith Construction and Son is the excavator. Their AVR states, “8/8/2025 Emergency OneCall was placed to dig at the intersection of Lakeview Dr. and Laurel Dr. While digging on Lakeview, an unmarked line was hit that resembled an underground power line.” Aqua Pennsylvania is the project owner. Their AVR states, “Aqua Contractor Smith Construction working under Emergency Ticket 20252202839 to repair a sewer blockage at the intersection of Lakeview Dr & Laurel Dr. USIC working for PP&L Electric responded to the emergency ticket, only marked out the telecom lines but not the power line. Crew started excavation and quickly hit an unmarked underground power line. PPL was contacted and their response was "cover it up, mark it well and we'll come back on Monday" since no one reported a power outage. Crew had no idea if line was old and abandoned or a live line. PPL refused to respond to immediately to the Damage Ticket which caused the Excavator to stop the excavation and delayed the work. USIC had a Foreman come back out to the site at some point and he located the line our contractor snagged, expressing disbelief that it was missed by the original USIC mark-out. PPL should have responded to the report of an electrical snag regardless of whether people lost power or not. PPL's refusal to respond should not limit our contractors ability to excavate and make the repair. If this had been an active powerline, a serious injury could have occurred.” Images submitted show a conduit that was pulled up with the bucket of an excavator. There are orange and green marks in the area, but not in the tolerance zone of the excavation. A water curbstop was uncovered directly beside the line that was damaged. No marks are visible to indicate this water line/curb stop. A utility cabinet shown in the ticket area on Google streetview. Images provided by PPL which were taken after the damaged occurred show red marks that were not present when the damage occurred. PPL was questioned on these marks and indicated the red marks that appear after the damage are for a PPL line lower than the damaged line. That line was not marked on the excavation Ticket # 20252202839. Ticket # 20252202839 was placed by Smith Construction to repair a sewer main for Aqua. PPL responded “Clear” to this ticket.	Section 2(5)(i) Subsequent \$2,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Ticket # 20252203585 New – Damage – Emergency 8/8/25, 8:21 PM. PPL responded “Field Marked” on 8/8/2025 at 8:37PM. Breezeline responded “Clear” on 8/12/2025. PPL’s 2(5)(i) violation is for not marking their lines on Ticket # 20252202839 Excavation– Emergency, as indicated by their response of “Clear”, but then marking their lines on Ticket #20252203585 Damage – Emergency as indicated by their response of “Field Marked”. This is also shown through images provided. Both tickets have the same location information and were called in the same day 6 hours apart from each other. Aqua’s 2(5)(i) violation is for not locating their line/curbstop on Ticket # 20252202839 as indicated through images provided. Violations: Facility – Aqua: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket # 20252202839 Recommendation: PUC Online Compliance Training is required. Facility – PPL: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. Ticket # 20252202839 Recommendation: PUC Online Compliance Training is required. Facility(other) – Breezeline: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket # 20252203585 Recommendation: PUC Online Compliance Training is required.	
57462	Facility Owner: Verizon Contractor/Excavator: R L E ENTERPRISES Project Owner: Pennsylvania American Water Company (PAWC) Other: Comcast Other: Plains Township Other: PPL Electric	<u>On 8/12/2025 9:00:00 AM at E CHARLES ST, PLAINS TWP, LUZERNE</u> On 2/10/26 The DPC voted to: Plains Township - \$1000.00 + Education Section 2(5)(vii) failure to respond to an emergency notification as soon as practicable ticket 20252241327 – 1st offense - \$1000.00 + Education Motion by Dacey to keep the violation, remove penalty. Keep the education requirement. Second by Bozic. ***** PPL provided documentation of communications with the excavator about complex meeting. DPI removed the violation and penalty. *** Plains Township is disputing. *** Incident occurred on August 12th, 2025, at 9am on East Charles Street, Plains Township, Luzerne County.	Verizon: \$8,000.00 Section 2(5)(i) Subsequent \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00 Section 2(10) Subsequent \$2,500.00 Section 2(5)(viii) 3rd Offense \$1,500.00 Pennsylvania American Water Company (PAWC): \$2,000.00 Section 4(2) 1st Offense \$500.00 Section 6.1(7) 2nd Offense \$1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		A telecom line was damaged. RLE Enterprises Alleged Violation Report (AVR) states, "WHILE DIGGING FOR A NEW WATER MAIN INSTALLATION, OUR CREW STRUCK AN UNMARKED VERIZON COMMUNICATIONS DUCK BANK. VERIZON WAS NOTIFIED AND ARRIVED ONSITE TO MAKE REPAIRS." PAWC's AVR submitted on 10/20/25 states, "RLE was digging for a tie in on E charles st and S main St in plains while digging the contractor hit a unmarked verizon line Verizon was contacted when they showed up verizon didnt think the line was active and was unsure if a fix was necessary verizon ended up fixing the line." Verizon's AVR submitted on 10/21/25 states, "This was initially marked as no conflict by a Verizon Technician. The in charge Verizon Technician was notified of the hit and consequently dispatched a technician to work on emergency repairs. However, due to the nature of the damage repairs were rescheduled to the following day. Damage was to split duct, fiber, and air pipe. The cable locates were listed with the city Moscow which caused the tickets to be initially mis-routed to the incorrect garage. The reason for the hit, not 100% certain but I believe there was a miscommunication/misunderstanding by splicer of where he thought the work was being done versus where the work actually was being done. Repairs were completed the following day. Attached are pictures of damage. The foreman inspected the site on 8/13/2025." Images show the damaged unmarked duct bank. Verizon responded clear to ticket 20252163080 when a line was damaged. Final design ticket was placed on 10/4/2024 and complex meeting was placed on 6/20/25. Violations: Verizon Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252163080. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work.	Comcast: \$4,500.00 Section 2(5)(v) Subsequent \$2,000.00 Section 2(5)(vii) Subsequent \$2,500.00 Plains Township: \$0.00 Section 2(5)(vii) 1st Offense \$0.00 PPL Electric: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20251712216. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). PAWC Section 6.1(7) – Project Owner failed to submit an Alleged Violation Report within 30 Days of a line strike. Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Comcast Section 2(5)(v) – Failed to respond to a routine One Call ticket. 20252163080. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252241327. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). Plains Township Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. 20252241327. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s). PPL Electric Section 2(5)(viii) – Failed to participate in preconstruction meetings for a complex project or as described in Section 5(3). 20251712216. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
58413	Facility Owner: Pennsylvania American Water (PAWC) Contractor/Excavator: SUSCO Project Owner: ARMSTRONG Other: Brightspeed	<u>On 8/25/2025 1:30:00 PM at SHAWNEE DR, CENTER TWP, BUTLER</u> On 2/10/26 The DPC voted to: PA American Water - \$500.00 (no education) Section 2(5)(i) failure to mark point of connection to main – 2nd offense 2025 - \$500.00 Motion by Dacey to accept the DPI’s recommendation. Second by Dippo. **** PAWC is disputing that it did not have records of the lines after purchasing them. Correction Water line was damaged. **** Incident occurred on August 25, 2025, at 1:30pm on Shawnee Drive, Center Township, Butler County.	Pennsylvania American Water (PAWC): \$500.00 Section 2(5)(i.1) 2nd Offense \$500.00 ARMSTRONG: \$500.00 Section 6.1(3) 1st Offense \$500.00 Brightspeed: \$500.00 Section 2(5)(v.2) 2nd Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		An Electric line was damaged. Susco's Alleged Violation Report had a blank summary. Armstrong's AVR states, "On August 25, 2025, our crew was set up at 128 Shawnee Drive. Utilities were located and marked prior to excavation. The team dug down on the marked water service and proceeded to begin drilling. During this process, the crew struck an unmarked water service line, located approximately 19 feet off the marked location. This resulted in water damage at the site." PAWC submitted an AVR on 10/30/25 that states, "The response for the ticket was no conflict. This area system was purchased from Center Township and the historical data that was received was minimal. PAWC is updating their system as replacement is being made. The curbox on PAWC side was not marked due to records not showing this information. We have updated our GIS records for this location. The line that was hit was on the customer owned side." Case is related to 58620. No design tickets were located by POCS for this complex project installation. Images show that the point of connection was marked outside of the tolerance zone. Violation: PAWC Section 2(5)(i.1) – Failed to locate an actually known facility’s point of connection to its facilities. Armstrong Section 6.1(3) – Released a project to bid or construction before final design was complete. PUC compliance education is required. Brightspeed Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests.20252304522. PUC compliance education is required for the individual(s) responsible to perform the locate for this ticket or their replacement(s).	
58204	Facility Owner: UGI Utilities Contractor/Excavator: WEXCON INC Project Owner: Stroud Township Sewer Authority Designer: REILLY ASSOCIATES - PITTSTON, PA	On 9/3/2025 12:45:00 PM at SCHUBERT RD, STROUD TWP, MONROE On 2/10/26 The DPC voted to: Motion by Ditty to: Stroud Township Water Authority 6.1(3)- Accept the DPI’s recommendation. Reilly Associates 4(2)- Accept the DPI’s recommendation. Second by Juergens. **** STSA is disputing. ***	WEXCON INC: \$500.00 Section 5(6)(ii) 1st Offense \$500.00 Stroud Township Sewer Authority: \$500.00 Section 6.1(3) 1st Offense \$500.00 REILLY ASSOCIATES - PITTSTON, PA: \$500.00 Section 4(2) 1st Offense \$500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Reilly Engineering is disputing. *** Incident occurred on September 3rd, 2025, at 12:45pm on Schubert Road, Stroud Township, Monroe County. A gas line was damaged. UGI's Alleged Violation Report (AVR) states, "Wexcon Inc. was digging to work on sewer and when digging a piece of macadam fell into the excavation and damage a gas service facility. Failure to protect an exposed facility." AVR states 911 was notified. Wexcon's AVR states, "While the crew was breaking for lunch, a side of the trench collapsed and a piece of asphalt from the road fell on the gas service and tore it in two. It was a newer service that automatically sealed shut. Foreman called the UGI emergency number on the UGI utility pole to alert UGI to the damage." Reilly Associates AVR placed on behalf of Stroud Township Sewer Authority states, "The trench was open in the ground and due to instability, a partial collapse led to a piece of asphalt from the road falling and hitting a gas lateral, breaking it. UGI was promptly called and the lateral was fixed the same day." Images provided show that the trench collapsed and damaged a non-protected gas line. A preliminary design ticket was placed by Reilly Associates, but no final design ticket was placed. Violations: Wexcon Section 5(6)(ii) – Excavator failed to provide support and mechanical protection for known facility owner’s lines at the construction work site. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Stroud Township Sewer Authority Section 6.1(3) – Released a project to bid or construction before final design was complete. 20242690104. PUC compliance education is required. Reilly Associates Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. 20242690104. PUC compliance education is required for the designer(s) who worked on this project or their replacement(s).	
58136	Facility Owner: Peoples Gas Company Contractor/Excavator: INDEPENDENT ENTERPRISES	<u>On 9/3/2025 9:30:00 PM at CATO ST, PITTSBURGH CITY, ALLEGHENY</u> On 2/10/26 The DPC voted to: Independent Enterprises - \$250.00 + Education Section 5(2.2) failure to provide exact information to identify the worksite – 1st offense - \$250.00 + Education	INDEPENDENT ENTERPRISES: \$500.00 Section 5(2.2) 1st Offense \$500.00 PITTSBURGH WATER:

Case Number	Stakeholders	Summary	Violations & Recommendation
	Project Owner: PITTSBURGH WATER	Motion by Bozic to accept the DPI's recommendation and add additional \$250 penalty for not attending the DPC meeting. Not in attendance Second by Clark. Original \$250 plus \$250 equals \$500. **** IEI is disputing. Please see where the sidewalk is in relation to the white dig area in the comparison pictures. *** Incident occurred on September 3rd, 2025, 9:30 pm, Cato Street, Pittsburgh City, Allegheny County. A gas line was damaged. Peoples Gas Company's Alleged Violation Report (AVR) states, "Independent Enterprises working tor Pittsburgh Water and Sewer Authority struck and damaged a Peoples Gas main line while working outside the proposed dig area. Independent called in an emergency on 8/27 for the following day, 8/28. The Peoples Gas locator spoke with the crew on site and was shown the white marked area in the middle of the street and marked accordingly. The service line near the work are was marked in white due to it being unlocateable and that was communicated with the crew on site. The locators notes are attached. Independent Enterprises then extended the dig area and never placed a new One Call request and struck the Peoples Gas mainline on 9/3, a full week after the initial emergency locate request." Independent Enterprises Inc AVR was submitted on 10/23/25 and states, "8:10PM - While performing excavation to repair a 6" WL, operator struck and broke unmarked 3" plastic gas line. Called 911. 8:20PM - Fire department arrives on site. 9:30PM - PNG rep on site. 11:15PM - PNG crew arrives. 2:30AM - Gas Line repaired. Incorrect markouts (Gas line was not marked)" Pittsburgh Water's AVR was submitted on 10/30/25 and states, "8:10PM - While performing excavation to repair a 6" WL, operator struck and broke unmarked 3" plastic gas line. Called 911. 8:20PM - Fire department arrives on site. 9:30PM - PNG rep on site. 11:15PM - PNG crew arrives. 2:30AM - Gas Line repaired. Incorrect markouts (Gas line was not marked)" Please see files named Comparison pic set 1 & 2. Images show that excavator marked in white for their excavation then went beyond their scope of work on the site. Peoples does have a yellow mark out going towards the site of the damage that is outside the scope of work. Pittsburgh Water was listed as the project owner "Work For--[PITTSBURGH WATER]" and received the emergency ticket that states a line was damaged.	\$1,500.00 Section 2(10) 2nd Offense \$1,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Pittsburgh Water submitted an AVR on 10/23/25. Pittsburgh Water also field marked on the emergency ticket that they are listed as the project owner on. Violations: Independent Enterprises Section 5(2.2) – Excavator failed to provide exact information to identify the worksite. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. Pittsburgh Water Section 2(10) – Facility owner failed to submit an Alleged Violation Report through the One Call System within 30 business days after receipt of notice that the facility owner’s lines have been damaged by excavation or demolition work or if the facility owner believes a violation of this act has been committed in association with excavation or demolition work. PUC compliance education is required for the person responsible for submitting AVR or their replacement.	
59624	Facility Owner: COMCAST Contractor/Excavator: UGI UTILITIES INC Project Owner: UGI UTILITIES INC	On 9/16/2025 9:02:00 AM at 1336 LOOP RD, LANCASTER CITY, LANCASTER UGI withdraw their dispute on 2/10/26 at 8:20am, agreeing to the violation and penalty ***** Disputing is UGI- see attachments ***** The incident occurred on Tuesday, September 16, 2025, at 9:02am, at 1336 Loop Road, in Lancaster City, Lancaster County. A cable and conduit owned by Comcast was damaged. Comcast stated in their Alleged Violation Report (AVR), an Excavator cut a cable and conduit. UGI Utilities stated in their AVR, while excavating for gas facilities, a UGI crew struck and damaged an unmarked conduit with black wire in it. A customer reported losing Comcast signal. Proper notifications were made, and Xfinity arrived to make repairs. This was not a project, rather, it was a single locate request at an address (1336 Loop Road) where we were relocating a small portion of service line. The length of the project is confined to a single ticket, 20252523076. The cost was under \$400k and would have used level C SUE. No complex project was established as it was a single locate request. The extent of the excavation, as listed on the ticket, is 5'X15', 911 was not notified as it is not required by law considering there is no hazardous release involved. The facility owner was notified via 811 under Damage Emergency tickets, 20252590896, 20252590898. Pictures provided by Comcast show the damage cable, and locate marks on 9/16/2025, the day of the damage.	COMCAST: \$4,000.00 Section 2(5)(i) Subsequent \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00 UGI UTILITIES INC: \$250.00 Section 5(20) 1st Offense \$250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Routine tickets- 20252523076 and 20252523075 placed on 9/9/2025, at 2:00pm, Lancaster City and Manheim Twp. Type of Work--[RELOCATE GAS SERVICE]. No Response from Comcast but responded late on 9/16/25 at 3:31pm as Field Marked. Damage Emergency tickets- 20252590896, 20252590898 placed on 9/16/2025, at 9:02am, Lancaster City and Manheim Twp. Remarks-- CALLER STATES THEY DAMAGED AN 1.25IN ORANGE CONDUIT WITH BLACK WIRE IN IT THAT WAS UNMARKED. CALLER STATES THE CUSTOMER HAS LOST COMCAST INTERNET. FACILITY TYPE: TELECOM-COMCAST Comcast responded at 3:31pm as Field Marked. Violations: *Comcast is in violation of sections: 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. 20252523076 and 20252523075 2(5)(v) – Failed to respond to a routine One Call ticket. 20252523076 and 20252523075 Recommendation: Penalties Applied *UGI Utilities is in violation of section: 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Recommendation: Penalty Applied. PUC Online Compliance Training is required for the Excavator(s) working onsite at this excavation, or their replacements.	
58964	Facility Owner: Columbia Gas Contractor/Excavator: Moon Twp Municipal Authority Project Owner: Moon Twp Municipal Authority	On 9/23/2025 9:57:00 AM at WALLRIDGE DR, MOON TWP, ALLEGHENY 2026 February Damage Prevention Committee - the DPC voted to keep Columbia's violation and remove penalty - keep education. ***** Columbia disputing ***** The incident occurred on 9/23/2025, at 9:57 AM, on Wallridge Dr, in Moon Twp, Allegheny County. A gas line owned by Columbia Gas was damaged. Columbia Gas is the facility owner. Their Alleged Violation Report (AVR) states, “Moon Township Municipal Authority was excavating as part of a water mainline project when they struck and damaged a 1.25-inch plastic gas main that had been inaccurately marked. Upon striking the facility, they promptly notified 911, 811, and Columbia Gas. Columbia Gas responded immediately to secure the area and complete necessary repairs. Further investigation revealed that the locating equipment was placing the facility in the incorrect location. This issue was able to be replicated at the time of the incident, confirming that the locate device signal matched the inaccurate placement.”	Columbia Gas: \$0.00 Section 2(5)(i) 2nd Offense \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Moon Township Municipal Authority is the excavator and project owner. Their AVR states, "The MTMA was excavating at the intersection of W. Crestridge and Wallridge Dr in Moon Twp Pa when the MTMA struck a mismarked Columbia Gas 1.25" plastic gas main that was feeding W. Crestridge Dr. MTMA struck the mismarked gas line outside of the tolerance zone. Excavation within the tolerance zone was done by hand digging. Please note the mark in the MTMA pictures was a T fitting and the branch gas line for W. Cresridge Drive (Noted with our hit kit "MARK" marker.) The gas line that was actually damaged was the branch line on the T mark. The main gas line marked along the asphalt curb line was for Wallridge dr. The gas line that was struck was for W. Crestridge Drive, a branch off of the Wallridge Dr gas main. The mark for the branch line was marked with a yellow T and was located 27" from the hit facility as indicated in the pictures. The strike was also 24" from the mark for the other gas line that travels along Wallridge Dr, which should be noted because it was not actually the mark for the line that was struck, it was for an entirely different gas line as you can tell by the travel path of the gas line as compared to the mark. The facility hit was outside of the tolerance zone from these marks as well. The hit facility was not within 18" tolerance zone of any of the gas marks at the site and MTMA was hand digging within the tolerance zone when working in the tolerance zone." Images submitted show the excavation, marks, and damaged line. The images support the statements in the AVRs. Violations: Facility – Columbia Gas: Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
59287	Facility Owner: Comcast Contractor/Excavator: Kriger Construction Inc Project Owner: Luzerne County Designer: ALFRED BENESCH AND COMPANY Other: AT&T Other: Frontier Communications Other: Giga Power Other: LUMEN Other: PPL Other: SERVICE ELECTRIC Cable TV & Communications (SECTV) Other: UGI UTILITES INC (ELECTRIC) Other: Verizon	On 10/2/2025 8:30:00 AM at <u>LASLEY AVE, HANOVER TWP, LUZERNE</u> On 2/10/2026 the Damage Prevention Committee voted to accept the Damage Prevention Investigator's recommendation as written. * AT&T disputed the fine "due to informational error". PPL disagreed and provided the documented mutual communication with the excavator. The violation is withdrawn. ALFRED BENESCH AND COMPANY disagreed. Offense and penalty were changed from a second offense and penalty of \$1000 to a first offense violation with a penalty of \$500. Violation in case 48445 was withdrawn during the stakeholder review. Alfred Benesch accepted this offer. *****	Comcast: \$3,500.00 Section 2(5)(v) Subsequent \$2,000.00 Section 2(5)(i) 3rd Offense \$1,500.00 Kriger Construction Inc: \$500.00 Section 5(20) 1st Offense \$250.00 Section 5(6)(i) 1st Offense \$250.00 Luzerne County: \$500.00 Section 6.1(3) 1st Offense \$500.00 ALFRED BENESCH

Case Number	Stakeholders	Summary	Violations & Recommendation
		The incident occurred on 10/02/2025 on Lasley Ave in Hannover Township in Luzerne County. A Communications coaxial line was damaged. KRIGER CONSTRUCTION INC the excavator, submitted an Alleged Violation Report (AVR) that included no summary, except for ticket “20211022006”. The work being done is described as “SHOULDER WIDENING for PennDOT using a milling machine. ALFRED BENESCH AND COMPANY the designer, stated in their AVR that “Project Design began in 2021. Preliminary PA One Call Serial No. is 20211022074. Comcast indicated clear-no facilities. PA One Call ticket was updated for final design - Serial No. 20233411716. Draft plans and a location map were provided with this PA One Call notification. All utilities were additionally cleared through the PennDOT Utility Relocation Management System (URMS). Notification letters for Utility Engineering Authorization were sent to Comcast on September 25, 2024, and the final PennDOT D-419 (Utility Clearance Form) was issued on May 7, 2025, in which Comcast was determined to be clear. On October 2, 2025, immediately following an onsite utility meeting for a separate portion of this project, we were notified of a utility hit from Kriger Construction milling machine to a Comcast conduit. It was measured that the conduit was less than 12" in many locations. Comcast was notified within minutes of learning of the utility hit and a maintenance worker, followed by a supervisor, arrived on site. Kriger Construction allowed Comcast to re-establish connection to their customers”. Pictures were provided. Above ground survey was noted as used. Project cost was listed as <\$400,000. ALFRED BENESCH AND COMPANY submitted a second AVR that stated that they area representing the Project Owner naming Luzerne County. They repeated what was in the first AVR stating that “Project Design began in 2021. Benesch placed a Preliminary PA One Call Serial No. is 20211022074. Benesch informed the County that Comcast indicated clear-no facilities. PA One Call ticket was updated for final design - Serial No. 20233411716 which included draft plans and a location map by Benesch. Luzerne County attended monthly status meeting with Benesch and PennDOT and were informed that all utilities were cleared through the PennDOT Utility Relocation Management System (URMS). Benesch issued notification letters for Utility Engineering Authorization to Comcast on September 25, 2024, and the final PennDOT D-419 (Utility Clearance Form) was issued on May 7, 2025, in which Comcast was determined to be clear. Luzerne County was informed that on October 2, 2025, a utility/Comcast conduit was hit by Kriger Construction's milling operation. A Luzerne County Representative, Vince Zerblas, came to the site and was present when it was measured that the conduit was less than 12" in many locations. Comcast was notified within minutes of learning of the utility hit and a maintenance worker,	AND COMPANY: \$500.00 Section 4(2) 1st Offense \$500.00 AT&T: \$1,500.00 Section 2(5)(v) 3rd Offense \$1,500.00 Frontier Communications: \$250.00 Section 2(5)(iii.1) 1st Offense \$250.00 Giga Power: \$250.00 Section 2(5)(iii.1) 1st Offense \$250.00 LUMEN: \$1,500.00 Section 2(5)(v) 3rd Offense \$1,500.00 PPL: \$0.00 SERVICE ELECTRIC Cable TV & Communications (SECTV): \$250.00 Section 2(5)(iii.1) 1st Offense \$250.00 UGI UTILITES INC (ELECTRIC): \$250.00 Section 2(5)(v) 1st Offense \$250.00 Verizon: \$1,000.00 Section 2(5)(v) Subsequent \$1,000.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		followed by a supervisor, arrived on site. Kriger Construction allowed Comcast to re-establish connection to their customers". They state that the project is <\$400,000. A length of 1080 and that above ground survey was completed. COMCAST stated in their AVR that "n 10/2/2025, Comcast was notified that our lines had been struck in the Hanover Industrial Park in Hanover, Pa on Lasley Avenue. Our crews responded and confirmed that a coaxial line was hit by a road crew doing milling and paving work. Comcast confirmed our locator did not respond to the locate ticket prior to the lawful start date. They added that "Ticket was not responded to by CPS. Comcast has visible pedestals along the road sides". And that the excavator "Failed to plan the excavation or demolition work to avoid damage or minimize interference with a facility owner's facilities in a construction area". They also state that the line was "Embedded in concrete/asphalt pavement". HANOVER TOWNSHIP LUZERNE COUNTY, sent an AVR stating that "AVR2025OCT170024 this Alleged Violation Report was received 11-12-25 and in response Hanover Township is not the facility owner of the line strike in question. Luzerne County has ownership of this line within Lasley Ave". Hannover Township is not relevant in this case. Verizon submitted an AVR on 11/18/2025 - Verizon is an "Other" stakeholder on this case. VERIZON PENNSYLVANIA LLC submitted another AVR which stated that "Below is the response from the VZ local manager for this area. Spoke with my splicer. Our facilities were not in their path. However, according to my tech Service Electric had conduits that the contractor hit. Our copper feed is in the ROW and they were not milling near our facilities. Pictures attached from the site". Pictures were attached. TICKET INFORMATION *Final design tickets 20211022074 and 20233412056 list a project that is 40' X 4375'. *Ticket 20252723692 was submitted by KRIGER CONSTRUCTION INC on 9/29/2025 at 15:19 with a response due by 10/01/2025. Scheduled excavation is for 10/02/2025 at 7 a. m. Incident occurred on 10/02/2025 at 8:30 a.m. Ticket states that work will be 1000 FEET ON LASLEY AVE and is expected to take a month to complete. Lumen never responded. UGI electric did not respond until 10/02/2025 Service Electric responded with a "conflict" on 9/29/2025 but never updated this response. PPL Electric responded "clear" on 10/02/2025. Giga Power scheduled mark on 10/01/2025, and on 10/02/2025 responded "clear" at 18:42 p.m. Frontier Communications scheduled mark on 10/01/2025, and on 10/02/2025 responded "clear" at 19:18 p.m.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		AT&T never responded. Comcast never responded. Verizon did not respond until the responded “clear” on 10/02/2025 at 15:30. VIOLATIONS Kriger Construction is in violation of: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. Section 5(20) – Excavator failed to renotify One Call of an unmarked or incorrectly marked facility upon arrival at a work site. Multiple facility owners did not respond to OneCall ticket 20252723692, including Comcast. Recommendations: The penalties are applied. The required excavator education was due by 8/07/2023 and has not been completed as of 10/21/2025. PUC compliance education is required for the excavators working onsite of this excavation or their replacements. ALFRED BENESCH AND COMPANY is in violation of: Section 4(2) – Designer failed to request the line and facility information prescribed by section 2(4) from the One Call System not less than ten nor more than ninety business days before final design is to be completed. Per ALFRED BENESCH AND COMPANY AVR “All utilities were additionally cleared through the PennDOT Utility Relocation Management System (URMS). Notification letters for Utility Engineering Authorization were sent to Comcast on September 25, 2024, and the final PennDOT D-419 (Utility Clearance Form) was issued on May 7, 2025, in which Comcast was determined to be clear. Final design was submitted by on ALFRED BENESCH AND COMPANY on 12/07/2023. On Sept 25, 2024 all utilities were additionally cleared through the PennDOT URMS. Final design ticket 20233412056 was submitted on 12/07/2023. This is 201 business days from 9/25/2024 and even more days from 5/07/2025. Final Design Ticket needs to be submitted through the OneCall system to notify all utilities. This is a second time offense. Recommendations: The penalty is applied. The required Designer education has recently been completed. Offense and penalty were changed from a second offense and penalty of \$1000 to a first offense violation with a penalty of \$500. Luzerne County is in violation of: Section 6.1(3) – Released a project to bid or construction before final design was complete. ALFRED BENESCH AND COMPANY did not submit a design ticket through OneCall System within 10-90 days before construction. The penalty is applied. Project owner education is required. Comcast Cable Communications Management, LLC is in violation of:	

Case Number	Stakeholders	Summary	Violations & Recommendation
		Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692. This is a subsequent offense. Section 2(5)(i) – Failed to locate underground lines within 18 inches horizontally of the outside wall of line. This is a third offense. Recommendation: The penalty is applied. Facility owner education is required. UGI UTILITES INC is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692 within the required amount of time. Ticket response due by 10/01/2025. UGI electric did not respond until 10/02/2025. Recommendation: The penalty is applied. Facility owner training is required. SERVICE ELECTRIC Cable TV & Communications (SECTV) is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252723692 had responded that there is a conflict. No other information provided. Recommendation: The penalty is applied. The required facility owner training was recently completed. PPL is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. Ticket 20252723692 was responded to, that the lines will be marked by 10/03/2025. There is no mutual communication noted. This is a second time offense. Recommendation: The penalty is applied. Facility owner training was recently completed. Giga Power is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. On 10/01/2025 Ticket 20252723692 was responded to, that the lines will be marked by 10/03/2025. There is no mutual communication noted. Ticket response and markings were due by 10/01/2025. Recommendation: The penalty is applied. Facility owner training is required. Frontier Communications is in violation of: Section 2(5)(iii.1) – Facility owner failed to propose a mutually agreeable scheduling by which the excavator, facility owner or designer may locate the facilities. On 10/01/2025 Ticket 20252723692 was responded to, that the lines will be marked by 10/03/2025. There is no mutual communication noted. Ticket response and markings were due by 10/01/2025. Recommendations: The penalty is applied. Frontier Communications has not completed any of the required training as of 10/21/2025. Facility owner and designer education was due by 7/14/2025. Project owner education was due by 10/07/2024. Training is required.	

Case Number	Stakeholders	Summary	Violations & Recommendation
		AT&T is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692. This is a third-time offense. Recommendation: The penalty is applied. Facility owner education was recently completed. Comcast is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692. This is a subsequent offense. Recommendation: The penalty is applied. Facility owner training is required. Verizon is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692 within the required amount of time. Verizon responded “clear” on 10/02/2025 at 3:30. Ticket response and markings were due by 10/01/2025. This is a subsequent offense. Recommendation: The penalty is applied. The required facility owner training has been recently completed. LUMEN is in violation of: Section 2(5)(v) – Failed to respond to routine One Call ticket 20252723692. This is a third time offense. Recommendation: The penalty is applied. Facility owner training is due by 11/09/2025 from case 54115.	
59124	Contractor/Excavator: A H MOYER Project Owner: Garden Oaks Apartments Other: Comcast Other: Met-Ed First Energy Other: Verizon	<u>On 10/7/2025 4:38:00 PM at 1605 GREEN LN, LEBANON CITY, LEBANON</u> 2026 February Damage Prevention Committee - the DPC voted to removed Met-Ed's violation. **** Met-Ed sent in additional information. A reduction to 2(5)(vii) penalty from \$1500 to a warning of \$0 was offered due to the information they provided. No response from Met-ed to the email. A second email was sent and no response was received. Currently listed as disputing the original violation of a 2nd warning of \$1500. ***** The incident occurred on 10/7/2025, at 4:38 PM, on 1605 Green Ln, in Lebanon City, Lebanon County. The incident is in reference to emergency ticket responses and markouts. A H Moyer is the excavator. Their AVR states, “comcast did not respond to and emergency locate request.... like normal and i put in a renotify, they didnt respond to that either.” Garden Oaks is listed as the project owner on the ticket. Ticket #20252803680 New – Excavation– Emergency was entered on 10/7/2025 at 2:37 PM. Ticket #20252803680 Renotify – Excavation – Emergency was entered on 10/7/25 at 4:29 PM. Comcast responded “Clear” on 10/14/2025. Verizon responded “Clear” on 10/8/2025. Met-Ed responded “Clear” on 10/7/2025 at 4:49PM.	Comcast: \$2,000.00 Section 2(5)(vii) 3rd Offense \$2,000.00 Met-Ed First Energy: \$0.00 Verizon: \$2,500.00 Section 2(5)(vii) Subsequent \$2,500.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Comcast submitted an AVR on 10/31/2025 that stated, "It seems that A H Moyer hit a water line at Garden Oaks in Lebanon City, PA. Notified by PA PUC of an emergency hit. All information is unknown due to lack of information in the emergency ticket." Violations: Facility(other) -Comcast: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252803680 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) -Verizon: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252803680 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) – Met Ed: Section 2(5)(vii) – Failed to respond to an emergency notification as soon as practicable following notification. Ticket #20252803680 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
59340	Facility Owner: SAINT MARYS TELEVISION Contractor/Excavator: Windstream Project Owner: Windstream - Placeholder Other: Comcast Other: National Fuel Gas	<u>On 10/13/2025 3:53:00 PM at TERRACE RD, ST MARYS CITY, ELK</u> 2026 February Damage Prevention Committee - the DPC voted to remove National Fuel's violation. ***** National Fuel Gas - disputing ***** The incident occurred on 10/13/2025, at 3:53 PM, on Terrace Rd, in St Marys City, Elk County. This incident is in reference to ticket responses and mark outs. No damage occurred. Windstream is the excavator and project owner. Their Alleged Violation Report (AVR) states, "Saint Mary's TV (Zito Media) continually fails to mark out their lines. They get the notification from 811 and always respond back no facilities field clear. We know for certain that is not the case because one of their workers have been here before to mark out their lines. This work site is located on and near East condot Rd, saint Mary's Pa. Both us (Windstream) and Zito media are the internet providers in this area. Saint Mary's Tv would have gotten the re-notification and still never came out." Ticket #20252803883 originally had a response due date of 10/9/2025, and a renotify was entered on 10/13/2025 at 1:52PM that states, "ATTN SAINT MARYS	SAINT MARYS TELEVISION: \$500.00 Section 2(5)(v.1) 1st Offense \$500.00 Comcast: \$2,000.00 Section 2(5)(v) Subsequent \$2,000.00 National Fuel Gas: \$0.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		TELEVISION YOU RESPONDED AS CLEAR NO FACILITIES. CALLER STATES THAT HE REACHED OUT TO SAINT MARYS TELEVISION TODAY OCTOBER 13 AND WAS TOLD THAT SOMEONE WOULD BE OUT TO MARK LINES BUT NO ONE HAS COME TO THE SITE. CALLER STATES THERE ARE DEFINITELY UG LINES AT THIS LOCATION. PLEASE VISIT THE SITE ASAP TO CHECK AND MARK ALL UG LINES. PLEASE RESPOND ASAP AS CREW WILL BE ON SITE TOMORROW OCTOBER 14 BY 0600 AND WILL START DIGGING BY 0700.” -Saint Marys Television responded “Clear” on 10/8/2025 to the routine ticket. They did not respond to the Renotify ticket within 2 hours, and entered a response of “Clear” on 10/14/2025 at 5:46 AM. -Comcast did not respond to the routine ticket, and National Fuel Gas responded “Conflict.” On 10/8/2025 but did not finalize their ticket response with “Clear” or “Field Marked”. Violations: Facility(other) - Saint Marys Television: Section 2(5)(v.1) – Failed to communicate directly with excavator within 2 hours of renotification. Ticket #20252803883-001 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) – Comcast: Section 2(5)(v) – Failed to respond to a routine One Call ticket. Ticket #20252803883-000 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s). Facility(other) - National Fuel Gas: Section 2(5)(v.2) – Failed to timely enter a final response to all locate requests. Ticket #20252803883-000 PUC online Compliance Training is required for the individual(s) responsible to perform the locate for this ticket, or their replacement(s).	
59383	Facility Owner: Peoples Gas Contractor/Excavator: Independent Enterprises Project Owner: Pittsburgh Water	On 10/14/2025 2:00:00 PM at LABELLE ST, PITTSBURGH CITY, ALLEGHENY 2026 February Damage Prevention Committee - Independent Enterprise did not attend to discuss their case - Violation raised from \$1000 to \$2000 due to previous multiple unpaid violations, and added \$250 for disputing but not attending for a total of \$2250. ***** Independent Enterprise - Disputing ***** The incident occurred on 10/14/2025 on Labelle St, in Pittsburgh City, Allegheny County. A gas line owned by the homeowner was damaged. 911 was contacted.	Independent Enterprises: \$2,250.00 Section 5(6)(i) 3rd Offense \$2,250.00

Case Number	Stakeholders	Summary	Violations & Recommendation
		Peoples Natural Gas submitted an Alleged Violation Report (AVR) that states, “Independent Enterprises working for Pittsburgh Water and Sewer struck and damaged a customer side plastic gas service line. Peoples Gas marked to the curb box, there was no wire and no drawing on the customer side.” Independent Enterprises is the excavator. An AVR has not been filed as of 11/07/2025 and an AVR request letter was sent the same day. Independent Enterprises responded and stated multiple times they are not required to submit an AVR. Indicating they will not be submitting an AVR, though they submitted one on 11/7/2025 that states, "On 10/14 around 1:35pm, IEI struck a mismarked gas line on the private side at 328 Labelle St while replacing water service line. The line is marked to the main and behind the curb box but was going down the sidewalk instead of where it was marked. IEI then stopped all work and called 911 non-emergency services. Around 1:45PM the fire department arrived on site. The fire department dispatched People's gas. Around 1:57PM, Peoples gas arrived on site and assessed the damage. People's Gas told IEI to replace the line due to the location being on the private side and the lack of materials available at the time. Around 2:15PM, People's gas shut the gas line off and the homeowner was notified by IEI that they will be out of gas until tomorrow and the homeowner was okay with this. The contractor began working on replacing the gas line. Around 3:15PM, IEI stopped the gas line replacement to continue working on their water line replacement. On 10/15 around 8:00AM, IEI returned to work on installing the new gas line. Around 9:30AM IEI had the new gas line installed and waited for inspection by People's Gas. While IEI waited they continued on with their water line service replacement. People's Gas did not show up and homeowner was notified that gas service would not be complete until the next day. On 10/16 around 1:25PM, People's gas hooked up the gas line and turned it on for the customer. The contractor made their way over to backfill. Foreman stopped all work and all equipment for safety concerns. 911 was notified by the contractor. CI notified CM team of incident. CI began creating IR to document incident." Pittsburgh Water is the project owner. An AVR has not been filed as of 11/07/2025. An AVR request letter was sent and an AVR was received on 11/7/25 that states, “Independent digging to install private side water service line and hit an unmarked/mismarked private side gas. Gas line came from the C/B and made a sharp left turn. Peoples Gas responded, made temp repairs and a new line was ran to the house.” Images provided show the area, damage, and repair after excavation occurred. No information or images are provided that show Independent Enterprises used like prudent techniques while excavating near the home 328 Labelle Street. A curb stop, and gas meter indicate that there are lines in the area. Additionally, no information	

Case Number	Stakeholders	Summary	Violations & Recommendation
		was provided to show that Independent Enterprises planned the excavation to damage to or minimize interference to the gas line to 328 Labelle Street. This case is related to case 056265 by a Complex Project ticket. Violations: Excavator – Independent Enterprises: Section 5(6)(i) – Excavator failed to plan the excavation or demolition work to avoid damage to or minimize interference with a facility owner’s facilities in the construction area. PUC online Compliance Training is required for the excavator(s) working onsite at this excavation, or their replacements.	